

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

**Our File No:** CC6/AIG21004801/KPA3Q2  
**Date:** 24/06/2021

**REFERENCE**

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 2070149988   |
| <b>Claimant Vehicle No :</b> | SKL4209X                             | <b>Insured Vehicle No :</b> | SMW952C      |
| Date of Loss:                | 15/04/2021                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 1728998996SG |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SKL4209X</b>                   |             |                   |
| Make & Model:               | MERCEDES-BENZ C180, 1.6 (A)       | Engine No:  | 27491030054740    |
| Reg. Date:                  | 08/11/2013 (Man. Year: 2013)      | Chassis No: | WDD2043312G116484 |
| Colour:                     | Metallic Silver                   | Odometer:   | 90344 km          |
| Engine Capacity:            | 1595 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |     |                         |     |                          |     |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition:       |     | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification:    | No  | Pre-accident Condition:  |     |

**CONDITION OF TYRES**

|                   |                  |                  |                  |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size:  | 225/45 R17       | Rear Tyre Size:  | 225/45 R17       |
| Front Left Side:  | Continental 8 mm | Rear Left Side:  | Continental 8 mm |
| Front Right Side: | Continental 8 mm | Rear Right Side: | Continental 8 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 19,573.00         | 6,065.00          | 13,508.00         | 69.01         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 6,950.00          | 3,420.00          | 3,530.00          | 50.79         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>26,523.00</b>  | <b>9,485.00</b>   | <b>17,038.00</b>  | <b>64.24</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>7,600.00</b>   |                   |               |

|                                                 |                  |                 |                  |              |
|-------------------------------------------------|------------------|-----------------|------------------|--------------|
| (S\$)                                           | 26,523.00        | 7,600.00        | 18,923.00        | 71.35        |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 1,856.61         | 532.00          | 1,324.61         | 71.35        |
| <b>Nett Amount (S\$)</b>                        | <b>28,379.61</b> | <b>8,132.00</b> | <b>20,247.61</b> | <b>71.35</b> |
| <b>+ Loss of Use (6.0 x S\$60.00/day) (S\$)</b> |                  | 360.00          |                  |              |
| <b>+ Medical Costs (S\$)</b>                    |                  | 34.50           |                  |              |
| <b>+ Doc/Search Fee (S\$)</b>                   |                  | 2.00            |                  |              |
| <b>Nett Liability (S\$)</b>                     |                  | <b>8,528.50</b> |                  |              |

INSPECTION

Date of Assignment: 16/04/2021

Date Inspected: 16/04/2021

Estimated Period of Repair: 6.0 days

Inspected At:

Goldbell Engineering Pte Ltd  
 Blk 5035 Ang Mo Kio Industrial Park 2  
 #01-367  
 Singapore 569538

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                                    | Condition          | Repairer's | Amount       |
|-----|-----|----------|------------------------------------------------|--------------------|------------|--------------|
| 1   | 1   |          | *BOOTLID                                       | Bent               | 3,465.00 F | *1,720.00 FL |
| 2   | 1   |          | *BOOTLID HINGE LH                              | Repair             | 280.00 F   | *- FL        |
| 3   | 1   |          | *BOOTLID HINGE RH                              | Repair             | 280.00 F   | *- FL        |
| 4   | 1   |          | *REAR EMBLEM -MERC                             | Necessary          | 87.50 F    | *40.00 FL    |
| 5   | 1   |          | *REAR EMBLEM -7 G-TRONIC                       | Necessary          | 157.50 F   | *129.00 FL   |
| 6   | 1   |          | *REAR EMBLEM -C&C                              | Necessary          | 85.00 F    | *85.00 FL    |
| 7   | 1   |          | *BOOTLID LOCK                                  | Repair             | 560.00 F   | *- FL        |
| 8   | 1   |          | *BOOTLID CATCH                                 | Repair             | 52.50 F    | *- FL        |
| 9   | 1   |          | *BOOTLID HANDLE                                | Serviceable        | 245.00 F   | *- FL        |
| 10  | 1   |          | *BOOTLID HANDLE STRIP<br>(50%)                 | Distorted / Dented | 385.00 FS  | *81.00 FS    |
| 11  | 1   |          | *BOOTLID SEAL                                  | Serviceable        | 350.00 F   | *- FL        |
| 12  | 1   |          | *BOOTLID INSULATOR                             | Serviceable        | 455.00 F   | *- FL        |
| 13  | 1   |          | *REAR BUMPER                                   | Bent               | 2,205.00 F | *1,207.00 FL |
| 14  | 1   |          | *REAR BUMPER RETAINER LH                       | Distorted          | 85.00 F    | *85.00 FL    |
| 15  | 1   |          | *REAR BUMPER RETAINER RH                       | Distorted          | 85.00 F    | *85.00 FL    |
| 16  | 1   |          | *REAR BUMPER REINFORCEMENT                     | Bent               | 1,295.00 F | *588.00 FL   |
| 17  | 1   |          | *REAR END PANEL                                | Bent               | 2,520.00 F | *710.00 FL   |
| 18  | 1   |          | *REAR END PANEL TOP GARNISH                    | Distorted          | 227.50 F   | *123.00 FL   |
| 19  | 1   |          | *REAR BUMPER CHROME TRIM LH                    | Necessary          | 238.00 F   | *129.00 FL   |
| 20  | 1   |          | *REAR BUMPER CHROME TRIM RH                    | Necessary          | 238.00 F   | *129.00 FL   |
| 21  | 1   |          | *REAR BUMPER CHROME TRIM CENTER                | Cracked            | 336.00 F   | *182.00 FL   |
| 22  | 1   |          | *REAR BUMPER TOWING COVER                      | Serviceable        | 91.00 F    | *- FL        |
| 23  | 1   |          | *LUGGAGE COMPARTMENT INNER TRIM (COMPLETE SET) | Serviceable        | 1,520.00 F | *- FL        |
| 24  | 1   |          | *SPARE TYRE PANEL                              | Repair             | 525.00 F   | *- FL        |
| 25  | 1   |          | *TAILLAMP LH                                   | Broken             | 1,120.00 F | *748.00 FL   |
| 26  | 1   |          | *TAILLAMP RH                                   | Serviceable        | 1,120.00 F | *- FL        |
| 27  | 1   |          | *TAILLAMP PANEL LH                             | Repair             | 297.50 F   | *- FL        |
| 28  | 1   |          | *TAILLAMP PANEL RH                             | Repair             | 297.50 F   | *- FL        |
| 29  | 1   |          | *SET REAR BUMPER CLIPS                         | Necessary          | 30.00 FS   | *30.00 FS    |
| 30  | 1   |          | *SET BOOTLID INSULATOR CLIPS                   | Necessary          | 60.00 FS   | *60.00 FS    |
| 31  | 1   |          | *SET LUGGAGE COMPARTMENT INNER TRIM CLIPS      | Not Necessary      | 60.00 FS   | *- FS        |
| 32  | 1   |          | *SET REAR REVERSE SENSOR                       | Dented             | 500.00 FS  | *500.00 FS   |
| 33  | 1   |          | *BODY SEALANT                                  | Necessary          | 320.00 FS  | *30.00 FS    |

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$)** **19,573.00** **6,661.00**

Report was unsubmitted during this print-out.

| No.                                               | Qty | Part No. | Particulars | Condition | Repairer's | Amount   |
|---------------------------------------------------|-----|----------|-------------|-----------|------------|----------|
| - List Item Discount on L Items 0.00/10.00% (S\$) |     |          |             |           | 0.00       | 596.00   |
| Total Parts (S\$)                                 |     |          |             |           | 19,573.00  | 6,065.00 |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                                                     | Lab.Type | Repairer's      | Amount          |
|---------------------------------|-----------------------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <u>Labour Items</u>             |                                                                                                                 |          |                 |                 |
| 1                               | TO REMOVE ,REFIX & REPAIR AFFECTED DAMAGED PARTS INCLUDING KNOCK OUT ,WELD AND STRAIGHTEN ON THE AFFECTED PARTS | New      | 3,600.00        | 1,800.00        |
| 2                               | TO CHECK AND RECONNECT ALL NECESSARY WIRING                                                                     | New      | 200.00          | 20.00           |
| 3                               | TO CONDUCT DIAGNOSTIC TEST AND PROGRAMMING                                                                      | New      | 650.00          | 200.00          |
| 4                               | TO PUTTY ,CLEAN ,SPRAY PAINT AND POLISH ,ETC                                                                    | New      | 2,500.00        | 1,400.00        |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                                                 |          | <b>6,950.00</b> | <b>3,420.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >