

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

GAN HAN YEEN
6 CHESTNUT GARDENS
SINGAPORE 679231

Contact : 96887100

TP China.
Xiao Chen.

ESTIMATE

Repair Code : CLM16768

Date in : 12/04/2021

Vehicle Num. : SLR9476P

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31255712/LEB5955730

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Dented</i>	1	762.70	✓ 762.70
REAR BUMPER REFLECTOR L/R <i>LH cancelled</i>	2	141.10	14/10 282.20
REAR BUMPER SIDE COVER LH <i>Dented</i>	1	195.00	✓ 195.00
REAR BUMPER SIDE RETAINER L/R <i>LH cancelled</i>	2	23.00	23 46.00
REAR BUMPER UNDER COVER <i>Dented</i>	1	250.00	✓ 250.00
REAR END PANEL <i>Dented</i>	1	415.60	✓ 415.60
REAR END PANEL INNER TOP GARNISH <i>Cancelled</i>	1	98.00	✓ 98.00
REAR FLOOR PANEL COMPARTMENT TRAY GARNISH <i>Not needed</i>	1	485.30	+ 485.30
REAR FLOOR PANEL TOP BOARD COVER <i>Not needed</i>	1	430.30	+ 430.30
REAR LH FENDER ARCH GARNISH <i>Cancelled</i>	1	195.00	✓ 195.00
REAR LH FENDER INNER TRIM BOARD <i>Not needed</i>	1	295.00	+ 295.00
REAR LH TAILLAMP <i>Cancelled</i>	1	474.60	✓ 474.60
REAR TAILGATE <i>Dented</i>	1	953.30	✓ 953.30
REAR TAILGATE 'HYBRID' EMBLEM <i>Not needed</i>	1	75.80	✓ 75.80
REAR TAILGATE 'LOGO' EMBLEM <i>Not needed</i>	1	25.00	+ 25.00
REAR TAILGATE 'VEZEL' EMBLEM <i>Not needed</i>	1	56.20	✓ 56.20
REAR TAILGATE HINGES L/R <i>Not needed</i>	2	50.00	+ 100.00
REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R <i>Not needed</i>	2	18.50	+ 37.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GAN HAN YEEN
 6 CHESTNUT GARDENS
 SINGAPORE 679231

Contact : 96887100

ESTIMATE

Repair Code : CLM16768

Date in : 12/04/2021

Vehicle Num. : SLR9476P

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31255712/LEB5955730

REAR TAILGATE INNER TRIM BOARD	1	153.40	+	153.40
REAR TAILGATE LH REFLECTOR	1	413.20	+	413.20
REAR TAILGATE MECHANISM LOCK	1	180.00	+	180.00
REAR TAILGATE WEATHER STRIP	1	96.80	✓	96.80
REAR TAILGATE WINDSCREEN MOULDING L/R	2	50.00	✓	100.00
REAR TAILGATE WINDSCREEN MOULDING T/L	2	50.00	✓	100.00
Subtotal before discount				6,220.40
Percentage discount 20%				1,244.08
Sub-total 1				4,976.32
REAR BUMPER CLIPS - SET	1	50.00	30	50.00
REAR BUMPER REVERSE SENSOR	1	280.00	200	280.00
REAR FENDER INNER TRIM BOARD CLIPS L/R - SET	2	40.00	X	80.00
REAR LH FENDER ARCH GARNISH CLIPS - SET	1	30.00	20	30.00
REAR LH TAILLAMP CLIPS - SET	1	25.00	10	25.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET	1	50.00	+	50.00
REAR TAILGATE WINDSCREEN SEALANT	1	80.00	60	80.00

*** This is a computer-generated document which requires no signature.***



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

GAN HAN YEEN
6 CHESTNUT GARDENS
SINGAPORE 679231

Contact : 96887100

ESTIMATE

Repair Code : CLM16768

Date in : 12/04/2021

Vehicle Num. : SLR9476P

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31255712/LEB5955730

Subtotal before discount	595.00
Percentage discount 0%	0.00
Sub-total 2	595.00
Parts-total	5,571.32

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

Labour Total	2,530.00
Parts & Labour Total	8,101.32

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
H/s 16/04/21.
06 Days

Total: 5439.68
H/s: A.3K. ✓