



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21004804/Ktf3e2	
			Date: 06/07/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SME 245E	Veh. Inspected	SKX 6692G
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2101028/SYH	Excess (\$)	0.00
	Assign From	IRENE HENRY	Assign Date	16/04/2021
2. Vehicle Particulars & Condition				
	Make & Model	SUZUKI SWIFT (A)	c.c	1372
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	JSAFZC82S00325997	Colour	METALLIC GREY
	Odometer	27969 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/55 R16	YOKOHAMA	8 mm
	L/H Front Tyre	185/55 R16	YOKOHAMA	8 mm
	R/H Rear Tyre	185/55 R16	YOKOHAMA	8 mm
	L/H Rear Tyre	185/55 R16	YOKOHAMA	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	31/03/2021	Inspection Date	16/04/2021
	Survey held at	281 ALEXANDRA ROAD		
	Repairer	PREMIUM AUTOMOBILES PTE LTD		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	