



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel:6702 4282 Fax:6702 4202

TP chim.

61K8 1100292

Page No. 1

Vehicle No.

SLJ8934H HONDA SHUTTLE Denise

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR ADJUSTMENT
	PARTS (LIST ITEMS)			
1	REAR BUMPER <i>Dented</i>		1218.70	<i>1150</i>
2	REAR BUMPER SIDE RETAINER LH & RH @\$68.20 <i>RH dented</i>		136.40	<i>68.20</i>
2	REAR BUMPER SIDE GARNISH LH & RH @\$104.10 <i>RH cracked</i>		208.20	<i>104.10</i>
2	REAR BUMPER BRACKET LH & RH @\$85.60 <i>new</i>		171.20	<i>+</i>
2	REAR BUMPER SPONGE LH & RH @\$103.50 <i>RH cracked</i>		207.00	<i>103.50</i>
1	REAR BUMPER LOWER REFLECTOR COVER RH <i>cracked</i>		110.00	<i>+</i>
1	REAR BUMPER TOW COVER <i>new</i>		40.00	<i>+</i>
1	REAR TAILGATE <i>Dented</i>		1292.70	<i>1193.</i>
1	REAR TAILGATE INNER LOCK <i>new</i>		378.00	<i>+</i>
1	REAR TAILGATE INNER TRIMBOARD <i>cracked</i>		410.00	<i>320.</i>
2	REAR TAILGATE DAMPER LH & RH @\$300.00 <i>new</i>		600.00	<i>+</i>
1	REAR TAILGATE " SHUTTLE " EMBLEM <i>new</i>		72.00	<i>+</i>
1	REAR TAILGATE " HYBRID " EMBLEM <i>new</i>		80.10	<i>+</i>
1	REAR TAILGATE LOGO <i>new</i>		75.00	<i>+</i>
1	REAR TAILGATE CENTRE CHROME <i>new</i>		405.00	<i>+</i>
1	REAR TAILGATE WEATHERSTRIP <i>new</i>		232.80	<i>+</i>
2	REAR TAILGATE LAMP RH <i>cracked</i>		444.50	<i>+</i>
2	REAR TAILLAMP RH <i>cracked</i>		578.00	<i>+</i>
1	REAR END PANEL <i>Dented</i>		620.00	<i>+</i>
1	REAR SPARE TYRE WELL PANEL <i>new</i>		1003.80	<i>+</i>
1	REAR SPARE TYRE BOARD <i>new</i>		687.80	<i>+</i>
1	REAR WINDSCREEN MOULDING <i>new</i>		120.00	<i>+</i>
1	REAR FENDER RH <i>new</i>		1280.00	<i>+</i>
1	REAR FENDER TRIM BOARD RH <i>cracked</i>		549.80	<i>498.</i>
1	REAR TAILGATE UPPER SPOILER <i>new</i>		850.00	<i>+</i>
1	Taillamp Panel RH <i>Dented</i>			
		less	20%	20%
			11770.80	
			2354.16	
			9416.64	
	SPECIAL NETT ITEMS			
1 SET	REVERSE SENSOR <i>Damaged</i>		280.00	<i>200</i>
1 SET	REAR BUMPER CLIPS <i>new</i>		60.00	<i>30.</i>
1	REAR END PANEL SEALANT <i>new</i>		100.00	<i>60</i>
1 SET	REAR TAILGATE INNER TRIM CLIPS <i>new</i>		80.00	<i>30</i>
1	REAR WINDSCREEN SEALANT <i>new</i>		100.00	<i>60</i>
	Total Parts		10036.64	



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel: 6702 4282 Fax: 6702 4202

Page No. 2

Vehicle No. SLJ8934H HONDA SHUTTLE

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	OUR ASSESSMENT (\$\$)
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	1600.00	1200
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1400.00	1200
3	To remove and refix wiring at damaged areas	180.00 30	
4	To perform anti rust treatment on affected areas	150.00 120	
5	To remove and replace reverse sensor and reverse camera and check for proper function	150.00 100	
6	To remove and refix rear windscreen	120.00	
7	To conduct water seepage test	100.00 8	
8	To transfer rear boot mechanism	120.00 80	
9	To tuff coat	150.00 60	
10	To remove and refix rear spare tyre, spare tyre board, carpet trim to assist work load	180.00 80	
	Labour Total :	4150.00	
TOTAL (PARTS & LABOUR):		14186.64	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj

Y/S 16/04/21.

07 Days ..

total: 8139.688

L/S: 6.5K

6.5K