

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Tham

Date: 21 Apr 2021

Preliminary Advice

Insured Vehicle No	: SMW6928J	Accident Date	: 26/03/2021
TP Vehicle No	: GBH5137R	Assignment Date	: 16/04/2021
Make	: TOYOTA HIACE	Est. Duration of Repair	: 3
Date of Inspection	: 20/04/2021		
Inspection At	: K KIM HIN AUTO PTE LTD BLK 34 SIN MING DRIVE,#01-114, SINGAPORE 575708		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,407.02
Revised Amount	:S\$	730.00
Check Items (Estimated)	:S\$	381.98
Total	:S\$	1,111.98

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :