

⏪	<	1 of 2 ?	>	⏩	↺	↻	100% ▼	📄 ▼	🖨	Find Next
---	---	----------	---	---	---	---	--------	-----	---	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL		Ref:	CS/SMO21004813/Ktf3
50 RAFFLES PLACE #03-03		Date:	16/04/2021
SINGAPORE LAND TOWERS SINGAPORE 048623		Code:	SMO
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	FBB 967B	Veh. Inspected	SMK 522Z
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2101151/RE	Excess (\$)	0.00
Assign From	IRENE HENRY	Assign Date	16/04/2021
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	10/04/2021	Inspection Date	19/04/2021
Survey held at	176 Sin Ming Drive #04-05 Sin Ming Autocare S57572		
Repairer	-		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			