



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIED WORLD ASSURANCE COMPANY LTD (SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSON SINGAPORE 079914			Ref: CS/AWA21004814/Etf3e2 Date: 28/04/2021 Code: AWA	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 6341X	Veh. Inspected	SBS 6022Z	
Policy No.	BVFCB0013692001	Coverage (\$)	0.00	
Claim No.	NSV2100050	Excess (\$)	0.00	
Assign From	PEGGY CHAN	Assign Date	16/04/2021	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ CITARO O530	c.c	6374	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	WEB62808323121952	Colour	MULTI COLOUR	
Odometer	156860 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	275/70 R22.5	BRIDGESTONE	4 mm	
L/H Front Tyre	275/70 R22.5	BRIDGESTONE	4 mm	
R/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	4/4 mm	
L/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	4/4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/04/2021	Inspection Date	16/04/2021	
Survey held at	550 Bukit Batok St 23, Singapore 659519			
Repairer	SBS TRANSIT LTD (Branch)			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days		