



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD
 (SINGAPORE BRANCH)
 60 ANSON ROAD #08-01 (8th FLOOR)
 MAPLETREE ANSON
 SINGAPORE 079914

Ref: CS/AWA21004814/Etf3
 Date: 16/04/2021
 Code: AWA

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YP 6341X	Veh. Inspected	SBS 6022Z
Policy No.	BVFCB0013692001	Coverage (\$)	0.00
Claim No.	NSV2100050	Excess (\$)	0.00
Assign From	PEGGY CHAN	Assign Date	16/04/2021

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	13/04/2021	Inspection Date	16/04/2021
Survey held at	550 Bukit Batok St 23, Singapore 659519		
Repairer	SBS TRANSIT LTD (Branch)		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
 B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.