





# TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE  
#15-08 WESTGATE TOWER  
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

## ESTIMATE

NO : QUOT202104-000027(00)

DATE : 15/04/2021

POLICY NO : 999995580

VEH REG NO : GBD7882E

MAKE/MODEL : MERCEDES BENZ CITAN 109  
CDI VAN EXTRA-LONG - 2  
SEATERS

CHASSIS NO : WDF4156052U146592

ENGINE NO : K9KB608D330571

REG. DATE : 2015

YOUR REF NO : GBE789H

CLAIM TYPE : THIRD PARTY

TP INS. CO. : CHINA TAIPING INSURANCE (SINGAPORE) PTE

ACCIDENT DATE : 12/04/2021

TP VEH REG NO : GBE789H

*Not Authorized  
U/Sing &  
Running After Pain*

*6 days*

## Estimate Repair Cost to Vehicle No : GBD7882E

Description	Quantity	Unit Price	Amount
		S\$	S\$
<b>NET PRICE</b>			
1 Rear door - LH	1	1,620.00	1,620.00 ✓
2 Rear door trimboard clips - LH	8	5.50	44.00 ✓
3 Rear door number plate lamp garnish - LH	1	205.00	205.00 x
4 Rear door 'CITAN' emblem - LH	1	58.00	58.00 ✓
5 Rear door - RH	1	1,080.00	1,080.00 ✓
6 Rear door '109 CDI' emblem - RH	1	62.00	62.00 ✓
7 Rear door inner trimboard clips - RH	8	5.50	44.00 ✓
8 Rear end panel (outer)	1	825.00	825.00 ?
9 Rear bumper	1	1,200.00	1,200.00 ✓
10 Rear bumper pad	1	580.00	580.00 ✓
11 Rear bumper reinforcement	1	338.00	338.00 ?
12 Rear bumper clips	15	9.00	135.00 ✓
			6,191.00
		Less 10%	619.10
			5,571.90
<b>SPECIAL NET</b>			
13 Rear door glass sealant - LH	1	40.00	40.00 ✓
14 Rear door 'C&C' emblem - LH	1	38.00	38.00 ✓
15 Rear door glass sealant - RH	1	40.00	40.00 ✓
16 Rear bumper sensor (set)	1	280.00	280.00 200.00
17 Rear door '4 paxs' sticker - LH	1	25.00	25.00 12.50
18 Rear door '70km/h' sticker - RH	1	25.00	25.00 12.50
			448.00
<b>LABOUR</b>			
19 To remove and refix both side rear door glass	1	160.00	160.00 120.00
20 To transfer damaged both rear door interior mechanism to new door	1	200.00	200.00 120.00
21 To remove and refix rear bumper sensor	1	80.00	80.00 50.00
22 To check and rectify wiring system	1	60.00	60.00 20.00
23 To panel beat and straighten rear floorboard panel, rear chassis frame, to cut and weld rear end panel, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00 ?
24 To putty and spray same on affected areas	1	1,200.00	1,200.00 800.00
25 To apply rust proofing on repaired and replaced panels	1	80.00	80.00 ?

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



# TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD  
1 GATEWAY DRIVE  
#15-08 WESTGATE TOWER  
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : GBE789H

CLAIM TYPE : THIRD PARTY

TP INS. CO. : CHINA TAIPING INSURANCE (SINGAPORE) PTE REG. DATE : 2015

ACCIDENT DATE : 12/04/2021

TP VEH REG NO : GBE789H

## ESTIMATE

NO : QUOT202104-000027(00)

DATE : 15/04/2021

POLICY NO : 999995580

VEH REG NO : GBD7882E

MAKE/MODEL : MERCEDES BENZ CITAN 109  
CDI VAN EXTRA-LONG - 2  
SEATERS

CHASSIS NO : WDF4156052U146592

ENGINE NO : K9KB608D330571

REG. DATE : 2015

## Estimate Repair Cost to Vehicle No : GBD7882E

Description	Quantity	Unit Price	Amount
		S\$	S\$
26 To supply & paste both side rear door sticker	1 <i>Mr</i>	480.00 ( <i>Bill</i> )	480.00 <i>7</i>
			3,260.00
		TOTAL	S\$ 9,279.90
		ADD GST @ 7%	649.59
		GRAND TOTAL	S\$ 9,929.49

SINGAPORE DOLLAR NINE THOUSAND NINE HUNDRED TWENTY-NINE AND CENTS FORTY-NINE ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORIZED SIGNATURE

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	12/04/2021 18:59 (SGT)
Date of Accident	12/04/2021 07:15 (SGT)
Exact Location of Accident	Sengkang, Singapore
Additional Location Information	SENGKANG EXIT TO KPE BEFORE ENTERING TUNNEL
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBD7882E
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	DAIMLER FLEET MANAGEMENT SINGAPORE PTE LTD
Company Reg No	1XXXXXX78Z
Email Address	derrick.lee@daimler.com
Mobile Phone No	(Phone) +65-68498118
Alternative Phone No	(Office) +65-68498118

## VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	Citan
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Reporting only
Vehicle Category	Commercial vehicle
Transmission	Auto
CC	1461

## INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	Yes
Policy Number	999995580
Cover Note Number	NA

## DRIVER

Name of Driver	TAN SOO WEI
NRIC No	SXXXX205B

Date Of Birth  
Occupation  
Date Of Driving Pass  
Driving experience  
Gender  
Mobile Number  
Alt. Phone Number  
Email Address  
Address  
Address complement  
Postcode  
Is the driver the policyholder?  
If No, Relationship of the Driver with the Insured  
Does Driver Own Other Vehicles?  
Vehicle Registration Number of Other Vehicle Owned by Driver  
Insurance Company of Other Vehicle Owned by Driver

24/09/1981  
Outdoor  
07/10/2004  
16 YEARS AND 6 MONTHS  
Female  
(Phone) +65-91519118  
-  
tan.karen@thepestman.com.sg  
NA  
-  
-  
No  
Hirer  
No  
-  
-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collision - Head to Rear  
Weather Conditions Raining  
Road Surface Wet

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident? No  
Number of vehicles involved in the accident 2  
Was anybody injured in the Accident? No  
Was any injured conveyed to hospital by ambulance? -  
Was any other material or property damaged? Yes  
Number of Passengers (Including Driver) 2  
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

#### PASSENGER 1

Name Xu Yi Guang  
Gender Male

#### DETAILS OF POLICE ACTION

Was the accident reported to the police? No  
Was notice of intended Prosecution given? No  
If yes, against whom? -

#### CIRCUMSTANCES OF ACCIDENT

I was driving slowly as it was raining and there was heavy traffic ahead. Upon the front vehicle brake, I also brake. Suddenly I felt an impact from my rear vehicle. I later realised that a silver lorry had hit the rear of my van.  
We exchange particulars.  
No injury involved.

#### ATTACHMENT(S)

Are accident photos available for attachment? Yes  
Was there any video captured by Car Camera? No  
Was there any audio recorded? No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBE789H  
Vehicle Manufacturer Nissan  
Vehicle Model Cabstar

SEN'S PARKS - GKD

TOWARDS KPE



A - GBD 7882E

B - GBE 789H.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO ATTACHED STATEMENT.

**DECLARATION**

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time: 12/4/21.

VERIFY BY AJAX MARS (ARC)  
REPORTING OFFICER  
MOHAMMAD AZALY BIN ABDULLAH  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.: