

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile CS3/ASM21004821/Gqc						
	AXA INSURANCE			Ref:	G <del>O/AGM21004021/Gqo</del>	
	8 SHENTON WAY AXA TOWERSING			Date:	16/04/2021	
				Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	YP 5702U	Veh. Inspected	l	FBS 3426L	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	S1M03860	Excess (\$)		0.00	
	Assign From	JOHNNY YONG (SMART CLAIMS)	Assign Date		16/04/2021	
2. Vehicle Particulars & Condition						
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5.	General Information					
	Accident Date	14/04/2021	Inspection Dat	е	16/04/2021	
	Survey held at	CANDYMOTOR WORKSHOP P	CANDYMOTOR WORKSHOP PTE LTD			
		25 KAKI BUIKIT ROAD 4 #01-83 SYNERGY @ KB SINGAPORE 417800				
5a. Rema			emarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					