

1/1p

AT AUTO CONSULTANT

Blk 113 Teck Whye Lane #05-650 Singapore 680113
 HP: 8386 8989 EMAIL: atautoconsultant@gmail.com
 Co. Reg. No. : 53368526E

Not Not have
 Runway After Rain
 & 500k

Date of Estimate: 15.04.2021
 Vehicle No: SLH9475U
 Owner: ISLAND CAR RENTAL & LEASING PTE LTD
 Date of Accident: 10.04.2021
 Make & Model: Honda Stream
 Chassis No : RN6-3116040

ESTIMATE FOR ACCIDENT VEHICLE NO SLH9745U

PARTS

1	1	Rear bumper(repair)	\$0.00
2	1	Rear fender RH(repair)	\$0.00
SUB TOTAL			\$0.00
LESS 20 %			\$0.00
DISCOUNTED SUB TOTAL			\$0.00

S. NETT ITEM

SUB TOTAL	\$0.00
LESS 0 %	\$0.00
DISCOUNTED SUB TOTAL	\$0.00

LABOUR

1	Panel beating for replace and repair affected parts	\$200.00
2	Spray painting on accident areas	\$400.00
3	Apply undercoating to above affected areas	\$100.00
SUB TOTAL (LABOUR)		\$700.00

100% ✓

SUB TOTAL (S.NETT) \$0.00

SUB TOTAL (PARTS) \$0.00

SUB TOTAL (LABOUR) \$700.00

ESTIMATED GRAND TOTAL \$700.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

PLEASE NOTE THAT THE ABOVE IS ONLY AN ESTIMATE. THEREFORE, SHOULD THERE BE ANY ADDITIONAL PARTS REQUIRE OR DISCOVER DAMAGE DURING OUR COURSE OF REPAIRS, WE WOULD INFORM YOU ACCORDINGLY FOR NECESSARY ACTION.
 PRICES OF PARTS QUOTED ARE SUBJECT TO CHANGE WITHOUT NOTICE.

APPROVING OFFICER SIGNATURE & COMPANY'S CHOP