

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST Reg No. 201629438M

09/04/2021

Owner: ALLIANCE LEASING PTE LTD

ESTIMATE TO REPAIR TOYOTA CAMRY 2.5A -SGR3056S

1pc rear LH door 1087.10
1pc rear LH door protector 288.20
1pc rear LH door protector chrome 65.00
12pcs front LH door frame top moulding rivet @\$8.00
1pc rear LH door inner rubber
1pc LH side skirt 617.80

Not Authorised
21 Apr @ 2400h
Resurvey After Paint
4 days

RM	\$	1,250.00	—
RM	\$	295.50	—
RM	\$	185.25	—
RM	\$	96.00	✓ 60
RM	\$	180.50	X
RM	\$	780.50	✓

less 25%

\$ 2,787.75

\$ 696.94

\$ 2,090.81

1pc Rear LH Sport rim

Red Sport rim \$ 650 280.00

remove & refit LH rear door glass
tuffkote
wiring
spray painting
labour charges

\$	120.00	60d
\$	80.00	30d
\$	120.00	20d
\$	1,000.00	600d
\$	1,000.00	450d

Total

\$ 4,410.81



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: