

FBQ 4508M

Aerox

Front Fork	350 / BT	Exhaust	280 X MN
Front Fork guard	110 60 / CNT	Exhaust cover	65 / cut
Front under Bracket	110 / BT	handle	110 / BT
Front wheel	220 / CNT	handle cover Front	68 / cut
Front Brake disc	110 / BT	handle cover Rear	68 / cut
Front ABS disc	75 X MN	meter	220 / cut
Front wheel Axle	45 / BT	seat	180 / TN
Front Head light	220 / OR	Cone Bearing	60 / 1PC
Front Head light stay	85 / BT	LOW	50 40
mirror RH	45 / CNT	Labour	500 300
Front mudguard	65 / OR	Frame repair	300 210
Front cowling LH	110 / BR		4562.00
Front cowling RH	110 / BR		
Front cowling center	65 / MIS		
Front side cover inner LH	85 / CRV		
Front side cover inner RH	85 / CRH		
Front cover upper, key hole	90		
Front cover lower	80		
Frame cover LH	70 X MN		
Frame cover RH	70 X MN		
Floor board LH	68 / CUT		
Floor board RH	68 / CUT		
under cover	85 / MIS		
under cover LH	70 / CUT		
under cover RH	70 / CUT		
Front signal RH	68 / CUT		
Front signal LH	68 / CUT		
Front mudguard LH	40 (Rear RH) - BR		
Front mudguard RH	40		
side cover LH	72 X MN		
side cover RH	72 / CUT		

paint

Parts - 3145
- 10%
2830.50

LH - 540
3370.50

L/S - 2696.40
= 2700

Steve (LKK) 19/4/21
w/L PL
L/S
3 dgs

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

FALCON

Acknowledged by Repairer

Signature:

Date: