



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2105294

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 29/07/2021
Reference CC6/CTI21004837/Aea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SMA 7583D
Insured Veh. SKZ 3719Z
Claim No. SNM21D202210/C02
Policy No. DMHCSNA00000752100
Accident Date 15/04/2021
Inspection Date 27/04/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21004837/Aea3q2	
			Date: 29/07/2021	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKZ 3719Z	Veh. Inspected	SMA 7583D	
Policy No.	DMHCSNA00000752100	Coverage (\$)	0.00	
Claim No.	SNM21D202210/C02	Excess (\$)	0.00	
Assign From		Assign Date	27/04/2021	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI AVANTE	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	KMH DU41BR9U749761	Colour	GREY	
Odometer	164044 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	KUMHO	6 mm	
L/H Front Tyre	225/45 R17	KUMHO	6 mm	
R/H Rear Tyre	225/45 R17	KUMHO	6 mm	
L/H Rear Tyre	225/45 R17	KUMHO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/04/2021	Inspection Date	27/04/2021	
Survey held at	MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMA 7583D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DISTORTED	486.90	486.90
2	REAR BUMPER SIDE HOLDER-LH & RH	NECESSARY	72.40	72.40
1	REAR BUMPER REINFORCEMENT	CRACKED	354.00	354.00
5	REAR BUMPER REINFORCEMENT BRACKET	DAMAGED	91.00	91.00
2	REAR BUMPER REINFORCEMENT STAY	N/S BENT	330.00	155.00
1	REAR END PANEL	DENTED	585.30	585.30
1	REAR END PANEL TOP GARNISH	DEFORMED	74.60	74.60
2	TAIL LAMP -LH & RH	N/S CRACKED	590.40	295.20
1	BOOTLID	TO REPAIR SEE LABOUR	907.20	-
1	BOOTLID LOCK	NOT NECESSARY	152.90	-
1	BOOTLID WEATHERSTRIPE	NOT NECESSARY	165.30	-
2	BOOTLID REFLECTOR-LH & RH	N/S CUT	481.60	240.80
2	BOOTLID HINGES -LH & RH	NOT NECESSARY	230.00	-
1	HYUNDAI LOGO	NECESSARY	35.60	35.60
1	AVANTE WORDING	NECESSARY	42.80	42.80
	LESS 20% DISCOUNT		-920.00	-486.72
			3,680.00	1,946.88
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	10.00	10.00
1	SET REAR END PANEL SEALANT (SN)	NECESSARY	60.00	60.00
			380.00	300.00
<u>LABOUR</u>				
	TO KNOCKING OUT REAR PORTION & RENEW ABOVE PARTS.INCLUSIVE OF THE REPAIR OF BOOTLID .		1,200.00	600.00
	TO PUTTY & SPRAY UP PAINT WORKS.		1,200.00	800.00
	TO CHECK WIRING SYSTEM.		50.00	30.00
	TO SPRAY TUFF COAT.		150.00	80.00
	TO REMOVE REVERSE SENSOR .		100.00	50.00

Report Ref No. CC6/CTI21004837/Aea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE UPHOLSTERY .		150.00	60.00
	TO TRANSFER BOOTLID FITTINGS.	NOT NECESSARY	150.00	-
	TO REMOVE REAR CAMERA.	NOT NECESSARY	100.00	-
			3,100.00	1,620.00
GRAND TOTAL			7,160.00	3,866.88
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,100.00

Report Ref No. CC6/CT121004837/Aea3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMA 7583D

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMA 7583D

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

