

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 Anson Road #16-00
 Springleaf Tower
 Singapore 079909
 Tel : 6389 - 6111
 Fax : 6224 - 7478 / 7175

Asher.

Quotation
 DATE : 27.04.2021
 VEH NO : SMA7583D
 MODEL : Hyundai Avante
 D O A : 15.04.2021
 YR REF : SKZ3719Z

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE: ESTIMATE FOR ACCIDENT REPAIR SMA7583D (HYUNDAI AVANTE)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Bumper <i>Distorted</i>	1	486.90 ✓
2	Rear Bumper Side Holder - LH & RH <i>new</i>	2	72.40 ✓
3	Rear Bumper Reinforcement <i>crushed</i>	1	354.00 ✓
4	Rear Bumper Reinforcement Bracket <i>Dented</i>	5	91.00 ✓
5	Rear Bumper Reinforcement Stay <i>LH Bent</i>	2	330.00 <i>155</i>
6	Rear End Panel <i>Dented</i>	1	585.30 ✓
7	Rear End Panel Top Garnish <i>Dented</i>	1	74.60 ✓
8	Tail Lamp - LH & RH <i>LH crushed</i>	2	590.40 <i>285.20</i>
9	Bootlid <i>Repair</i>	1	907.20 <i>x</i>
10	Bootlid Lock <i>3 new</i>	1	152.90 <i>x</i>
11	Bootlid Weatherstripe <i>3 new</i>	1	165.30 <i>x</i>
12	Bootlid Reflector - LH & RH <i>LH cut</i>	2	481.60 <i>240.80</i>
13	Bootlid Hinges - LH & RH <i>new</i>	2	230.00 <i>x</i>
14	Hyundai Logo <i>3 new</i>	1	35.60 ✓
15	Avante wording <i>3 new</i>	1	42.80 ✓
			<hr/>
			\$ 4,600.00
Less 20%			(920.00)
			<hr/>
			\$ 3,680.00
S/NET ITEMS			
1	Front Bumper Clips <i>new</i>	1set	30.00 ✓
2	Reverse Sensor <i>Damaged</i>	1	280.00 <i>200</i>
3	Rear end Panel Top Garnish Clips <i>new</i>	1 set	10.00 ✓
4	Rear End Panel Sealant <i>new</i>	1 set	60.00 ✓
			<hr/>
			\$ 380.00
Total parts			<hr/>
			\$ 4,060.00

LABOUR CHARGE

1 To knocking out rear portion & renew above parts \$ 1,200.00 *600*

RE : ESTIMATE FOR ACCIDENT REPAIR SMA7583D (HYUNDAI AVANTE)

2	To putty & spray up paint works	\$	1,200.00	80
3	To check wiring system	\$	50.00	30
4	To spray tuff coat	\$	150.00	80
5	To remove reverse sensor	\$	100.00	50
6	To remove upholstery	\$	150.00	60
7	To transfer bootlid fittings	\$	150.00	X
8	To remove rear camera	\$	100.00	X
Total Labour		\$	3,100.00	
Grand Total		\$	7,160.00	

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 3866.88
L/S: 3.11k.
05 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: