Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited From: LKK Auto Consultants Pte Ltd

10 Eunos Road 851 Ubi Ave 1 #01-25#09-04A Singapore Post CentrePaya Ubi Industrial ParkSingapore 408600Singapore 408933

Attn: Date: 22 Apr 2021

Preliminary Advice

Insured Vehicle No : SMN7559G

TP Vehicle No : SMX6857A Accident Date : 19/04/2021 Make : HONDA CIVIC Assignment Date : 22/04/2021

Date of Inspection : 19/04/2021 Est. Duration of Repair : 2

Inspection At : TRANS-CAB AUTO SERVICES PTE LTD

NO 2 ANG MO KIO STREET 63

SINGAPORE 569111

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,806.93
Revised Amount	:S\$	1,165.08
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,165.08

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

)	let us have your authorisation.
)	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
)	Other comments: