



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0330/2021/CCS
DATE : 16-Apr-21
WIP : 23463

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 16/4/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR CHUA YONG KIT
ADDRESS : 626 UPPER THOMSON ROAD
#04-26
SINGAPORE 787130
TELEPHONE : HP +65 88660020
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO :
VEHICLE NO : **SMW 952 C**
MODEL CODE : Q5 SPORT 2.0 TFSI
MODEL YEAR : 30/10/2020
ENGINE NO : DAX 060695
CHASSIS NO : WAUZZZF5L2007112
MILEAGE : -
DATE IN : 15-Apr-21
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 15-Apr-21
PLACE OF ACCIDENT : 1 ANG MO KIO AVE 8, SINGAPORE
CROSS JUNCTION OF ANG MO KIO AVE 1

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMW 952 C.

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HOURS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 ✓	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULES.	S/N \$ 800.00 250	
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00 ✓	
4	TO DISMANTLE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH SIDE MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOOR.	S/N \$ 800.00 560	
5	TO RENEW ENGINE MAGNET COVER AND OTHER ENGINE COMPONENTS.	S/N \$ 480.00 26 ?	
6	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 6,400.00 2500.	
SUB-TOTAL LABOUR CHARGES		: \$ 10,360.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMW 952 C.

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO RESPRAY FRONT BUMPER, FRONT LOWER SPOILER, BOTH FRONT FENDERS, BONNET, BONNET HINGES, BOTH FRONT WHEEL ARCH TRIMS, BOTH UPPER A-PILLARS AND BOTH FRONT DOORS. ✓✓	4525 7,500.00	Bumper 550 Fender 550 Door x 2 1100 Pillar x 2 1100 Spoiler 275 Bonnet 550
8	TO RECOVER AND TOW BACK VEHICLE FROM SCENE OF ACCIDENT. S/N \$	280.00	X Wheel Arch x 2 = 400 4525
9	TO CARRY OUT PRE-DIAGNOSTIC AND POST-DIAGNOSTIC CHECK. S/N \$	384.00	192.
TOTAL LABOUR CHARGES		: \$ 18,524.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 952 C

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER <i>Distorted</i>	1	\$	2,724.00	✓
2	FRONT BUMPER CONNECTING PIECE <i>could</i>	1	\$	205.00	✓
3	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$	393.00	?
4	FRONT BUMPER CLOSING ELEMENT - LH/RH <i>new</i>	2	\$	226.00	+
5	FRONT BUMPER GRILLE - CENTER LOWER <i>could</i>	1	\$	144.00	✓
6	FRONT BUMPER SPOILER <i>new</i>	1	\$	763.00	+
7	FRONT BUMPER UNDERRUN BAR <i>cut</i>	1	\$	518.00	✓
8	FRONT BUMPER CLOSING ELEMENT - LOWER <i>new</i>	1	\$	173.00	+
9	RADIATOR GRILLE <i>could</i>	1	\$	3,530.00	✓
10	QUATTRO ' INSCRIPTION <i>new</i>	1	\$	106.00	✓
11	RADIATOR GRILLE STRIKER PLATE <i>could</i>	1	\$	244.00	✓
12	FRONT BUMPER AIR GRILLE - LH/RH <i>cut</i>	2	\$	1,162.00	581
13	FRONT BUMPER GRILLE END CAP - LH/RH <i>new</i>	2	\$	184.00	+
14	FRONT BUMPER LOCKING CLIP <i>new</i>	4	\$	16.00	+
15	FRONT BUMPER FOAM - INNER <i>del</i>	1	\$	177.00	✓
16	FRONT REINFORCEMENT BEAM <i>del</i>	1	\$	981.00	✓
17	FRONT BUMPER GUIDE - LH/RH	2	\$	78.00	?
18	FRONT REINFORCEMENT BEAM BRACKET - LH/RH	2	\$	512.00	?
19	FRONT BUMPER TOP COVER <i>could</i>	1	\$	129.00	✓
20	SIGN ' CAUTION ' STICKER <i>new</i>	1	\$	14.00	✓
SUB-TOTAL SPARE PARTS		:	\$	12,279.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 952 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	STICKER FOR AIR CONDITIONER <i>N/A</i>	1	\$ 20.00	✓
22	WARNING SIGN FOR PEDESTRIAN PROTECTION <i>Not N/A</i>	1	\$ 30.00	+
23	FRONT BUMPER PARKING AID SENSOR ?	4	\$ 960.00	?
24	FRONT BUMPER SENSOR SEAL RING ?	4	\$ 14.00	?
25	WIRING SET FOR FRONT BUMPER <i>Not N/A</i>	1	\$ 409.00	+
26	HORN - LH/RH ?	2	\$ 390.00	?
27	FRONT FENDER - LH/RH <i>RH Regis</i>	2	\$ 2,854.00	+
28	FRONT FENDER BRACE - LH/RH	2	\$ 450.00	+
29	FRONT FENDER BRACKET - LH/RH <i>3 x 100</i>	2	\$ 36.00	+
30	FRONT WHEEL HOUSING LINER - LH/RH <i>100</i>	2	\$ 556.00	+
31	FRONT WHEEL HOUSING LINER ATTACHEMENT PART <i>Not N/A</i>	1	\$ 38.00	+
32	FRONT WHEEL SPOILER - LH/RH <i>Not N/A</i>	2	\$ 324.00	+
33	FRONT WHEEL ARCH TRIM - LH/RH <i>N/A</i>	2	\$ 1,264.00	✓
34	BONNET <i>Dented</i>	1	\$ 4,058.00	✓
35	BONNET HINGE - LH/RH <i>3 x 100</i>	2	\$ 322.00	+
36	BONNET ATTACHEMENT PARTS	1	\$ 141.00	+
37	BONNET LOCK STRIKER - LH/RH <i>RH Bent</i>	2	\$ 240.00	120.
38	BONNET SOUND ABSORBER <i>Not N/A</i>	1	\$ 317.00	+
39	BONNET IMPACT PROTECTION - LH/RH <i>3 x 100</i>	2	\$ 56.00	✓
40	BONNET IMPACT PROTECTION - CENTER	1	\$ 28.00	✓
SUB-TOTAL SPARE PARTS		:	\$ 12,507.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 952 C

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
41	PLENUM CHAMBER COVER <i>seen</i>	1	\$ 145.00	X	
42	BONNET LOCK	2	\$ 427.00	X	
43	BONNET BOWDEN CABLE	1	\$ 58.00	X	
44	BONNET RELEASE ELEMENT	1	\$ 58.00	X	
45	BONNET RELEASE LEVER <i>seen</i>	1	\$ 14.00	X	
46	BOWDEN CABLE COVER	1	\$ 10.00	X	
47	BONNET LOCK CABLE	1	\$ 74.00	X	
48	HEADLIGHT MOUNTING - LH/RH ?	2	\$ 236.00	X	
49	LED HEADLIGHT - LH/RH <i>RTI cracked</i>	2	\$ 16,382.00		8191
50	HEADLIGHT WASHER CYLINDER - LH/RH <i>seen</i>	2	\$ 280.00	X	
51	HEADLIGHT WASHER HOSE <i>seen</i>	1	\$ 125.00	X	
52	FRONT LOCK CARRIER <i>cracked</i>	1	\$ 1,400.00		
53	FRONT LOCK CARRIER BRACE - LOWER LH/RH <i>not seen</i>	2	\$ 114.00	X	
54	RADIATOR SUPPORT - LOWER LH/RH	2	\$ 106.00	?	
55	A/C CONDENSER ?	1	\$ 601.00	?	
56	A/C CONDENSER SEAL RING ?	2	\$ 17.00	?	
57	OUTER TEMP. SENSOR BRACKET ?	1	\$ 16.00	?	
58	CHARGE AIR COOLER <i>seen</i>	1	\$ 819.00	X	
59	RADIATOR	1	\$ 919.00	?	
60	COOLANT <i>seen</i>	1	\$ 269.00	?	
SUB-TOTAL SPARE PARTS		:	\$ 22,070.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 952 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	FAN RING ?	1	\$ 430.00	?
62	RADIATOR FAN WITH CONTROL UNIT ?	1	\$ 2,394.00	?
63	RADIATOR LOUVRE ?	1	\$ 534.00	?
64	RADIATOR AIR GUIDE - UPPER ?	1	\$ 48.00	?
65	RADIATOR AIR GUIDE - CENTER ?	1	\$ 42.00	?
66	RADIATOR AIR GUIDE - LOWER ?	1	\$ 48.00	?
67	RADIATOR AIR GUIDE - LH/RH ?	2	\$ 116.00	?
68	CAMSHAFT MAGNET COVER <i>new</i>	1	\$ 240.00	+
69	S-LINE' INSCRIPTION <i>RH new</i>	2	\$ 255.00 127.50	
70	FRONT DOOR WINDOW SLOT SEAL - LH/RH <i>LH ut</i>	2	\$ 1,232.00 616.	
71	ENGINE OIL <i>new</i>	1	\$ 180.00	✓
72	CAMSHAFT MAGNET ?	2	\$ 338.00	?
73	CONNECTOR FOR MAGNET ?	2	\$ 302.00	?
74	MAGNET COVER END CAP <i>cracked</i>	1	\$ 31.00	✓
75	INTAKE AIR DUCT ?	1	\$ 84.00	?
76	INTAKE AIR HOSE <i>new</i>	1	\$ 95.00	+
77	FRONT NUMBER PLATE <i>Derf</i>	S/N	\$ 60.00	✓
78	SUNDRIES ?		\$ 400.00	?
TOTAL SPARE PARTS		:	\$ 53,685.00	
TOTAL LABOUR CHARGES		:	\$ 18,524.00	
GRAND TOTAL		:	\$ 72,209.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Adrian Lj
16/04/21

not authorised, 11 days.

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT