

TP Budget Direct SFT2806 2018 Jan.

Veron Mercedes Benz C180 1595cc

WDD2050402R338097.

Front Number Plate	} NH or	30(SN) +
Front Number Plate Holder		30(SN) +
Front Number Plate Garnish		92 +
Front Bumper Del		1651 -
Front Bumper Clips. n		50(SN) -
Front Bumper Side Holder x 02	LH n	68 x 2 = 136. 68
Front Bumper Sensor x 03	1 piece and	250 x 3 = 750
Front Bumper Sensor Wire Harness	snapped	382 -
Front Bumper lower Grille. Del		182 -
Front Bumper Side Grille LH. Del		89 -
Front Bumper lower Chrome Garnish. ut		362 ✓
Front Bumper Undercover torn		228 -
Front Bumper Undercover Clips. n		30(SN) -

4012.00

SFT 280G

Front Bumper Sponge.	crushed	164	✓
Front Bumper Reinforcement	dented	520	✓
Front Bumper Reinforcement Stay	LH. ^{NE NE}	312	x
Front Bumper Inner Cover.	torn	185	✓
Front Grille	crushed	885	✓
Front Grille Logo	NA	128	✓
Front Grille Chrome Garnish.	^{MP} m	282	x
Front Grille Clips.	per	30 (sw)	✓
Headlamp x 02.	LH crushed	3654 x 2 = 7308	3280 3654
Headlamp Bracket x 02	^{LH} crushed	68 x 2 = 136	68
Bonnet	dented	2277.	✓
Bonnet Logo	NA	78	✓
Bonnet Lock LH.	^{MP} m	188	x
Front Support Panel Top Beam.	Dented	525	✓

12,818.00

SFT280G.

Front LH Fender Buckled.	948 ✓
Front LH Fender Inner Shield (Front)	135 ✓
Front LH Fender Inner Shield (Rear)	145 X
Front LH Fender Inner Shield clips.	50 (SW) / 25 (SN)

12579 S.N: 135
11321-10

Panel Beating	1000 800
Spray Painting.	1000 750
Wiring.	100 30
To remove front bumper sensor.	100 60
To perform diagnostic test.	150 100

3628.00

20,458.00

total: 13196.10

L/S: 10 SK.

08 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: