3/28/22, 11:23 PM Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21004846/TPA3Q2

**Date:** 28/03/2022

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070180559

Claimant Vehicle No : SHC6155L Insured Vehicle No : EE555E

Date of Loss: 19/03/2021 Nature of Claim: TP Claim No: 6145069044SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SHC6155L

Make & Model: KIA OPTIMA, 1.7 D (A) Engine No: D4FDDH308183

Reg. Date: 26/09/2014 (Man. Year: 2014) Chassis No: KNAGM414ME5468577

Colour: Silver Odometer: 0 km

Engine Capacity: 1685 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65 R15 Rear Tyre Size: 205/65 R15
Front Left Side: Maxxis 6 mm Rear Left Side: Maxxis 6 mm
Front Right Side: Maxxis 6 mm Rear Right Side: Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		1,365.60	30.00	1,335.60	97.80
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,210.00	680.00	530.00	43.80
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	2,575.60	710.00	1,865.60	72.43
	+ GST 7.00/7.00% (S\$)	180.29	49.70	130.59	72.43
	Nett Amount (S\$)	2,755.89	759.70	1,996.19	72.43
	+ Loss of Use (2.5 x S\$50.00/day) (S\$)		125.00		
	+ Car Rental (2.5 x	S\$62.76/day) (S\$)	156.90		
		(S\$)	1,041.60		
	Liable Amo	ount (50.00%) (S\$)	520.80		
	+ Do	c/Search Fee (S\$)	2.00		
		Nett Liability (S\$)	522.80		
	Global Sur	m Settlement (S\$)	500.00		

**INSPECTION** 

Date of Assignment: 19/04/2021

Premier Automotive Services Pte Ltd (HQ)

Date Inspected: 20/04/2021 Inspected At: 23 Changi South Ave 2, #01-02

Singapore 486443

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

#### **REPAIR DETAILS**

# **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER EMBLEM	Not Necessary	44.00 FL	*- FL
2	1		*FRONT BUMPER	Repair	531.00 FL	*- FL
3	1		*FRONT BUMPER N/S & O/S SIDE RETAINER	Not Necessary	32.00 FL	*- FL
4	1		*FRONT BUMPER N/S PROTECTOR	Not Necessary	51.00 FL	*- FL
5	1		*FRONT BUMPER N/S FOG LIGHT COVER	Not Necessary	66.00 FL	*- FL
6	1		*FRONT N/S FENDER INNER SHIELD	Not Necessary	120.00 FL	*- FL
7	1		*FRONT N/S FENDER	Repair	384.00 FL	*- FL
8	1		*FRONT N/S WHEEL COVER	Not Necessary	116.00 FL	*- FL
9	1		*FRONT BUMPER CLIPS	Not Necessary	48.00 FS	*- FS
10	1		*FRONT N/S FENDER STICKER	Necessary	30.00 FS	*30.00 FS
11	1		*SET FRONT N/S FENDER INNERSHIELD CLIPS	Not Necessary	28.00 FS	*- FS
12	1		*SUNDRY	Not Necessary	50.00 FS	*- FS
F=Fra	anchise	part. S=SpcN	lett. L=ListItemDisc.	-		
				Sub Total (S\$)	1,500.00	30.00
			- List Item Discount on L Ite	ms 10.00/10.00% (S\$)	134.40	0.00
				Total Parts (S\$)	1,365.60	30.00
			Report was unsubmitted during this	print-out.		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO CHECK FRONT N/S WHEEL ALIGNMENT	New	80.00	80.00
2	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR RESHAPE AND ADJUST OF THE SAME ,ETC	New	650.00	200.00
3	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER ,FRONT N/S FENDER	New	400.00	400.00
4	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	80.00	0.00
	Gross Labour	Cost (S\$)	1,210.00	680.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >