

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

20-Apr-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6155 L

1 pc	Front bumper emblem	\$	44.00	X un
1 pc	Front bumper	\$	531.00	By
1 pc	Front bumper n/s & o/s side retainer	\$	32.00	X
1 pc	Front bumper n/s protector	\$	51.00	X un
1 pc	Front bumper n/s fog light cover	\$	66.00	X
1 pc	Front n/s fender inner shield	\$	120.00	X
1 pc	Front n/s fender	\$	384.00	Ry
1 pc	Front n/s wheel cover	\$	116.00	X un
		\$	1,344.00	
		\$	134.40	Less 10%
		\$	1,209.60	
		\$	48.00	X un
		\$	30.00	ne
		\$	28.00	X un
		\$	50.00	X un
		\$	80.00	
		\$	650.00	200
		\$	400.00	400
		\$	80.00	X un
		\$	2,575.60	9710

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Taunhin 97115+492days
UP 20/4/21 @ 2:50pm
US Resurvey after repair
20 days
Taunhin 16/4/21