

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email : mg3solution@gmail.com

TO	: GREAT AMERICAN	DATE	: 16/04/2021
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: SJN5400D		
MODEL	: TOYOTA ALLION 1.5 A		
CHASSIS NO			
ACCIDENT DETAILS		DATE	: 15-Apr-21
		TIME	: 15:30HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOT LID <i>Dented</i>	1	\$ 1,122.00	\$ 1,122.00
2	BOOT LID LOGO	1	\$ 67.20	\$ 67.20
3	BOOT LID EMBLEM 'A15'	1	\$ 51.20	\$ 51.20
4	BOOT LID EMBLEM 'ALLION'	1	\$ 51.20	\$ 51.20
5	BOOT LID TOP LOCK <i>Damaged</i>	1	\$ 489.55	\$ 489.55
6	BOOT LID LOWER LOCK <i>new</i>	1	\$ 65.00	\$ 65.00
7	BOOT LID WEATHERSTRIP <i>new</i>	1	\$ 335.00	\$ 335.00
8	BOOTLID DETECTOR <i>At car</i>	1	\$ 230.50	\$ 230.50
9	BOOT LID CHROME MOULDING <i>Cracked</i>	1	\$ 240.60	\$ 240.60
10	REAR BUMPER <i>Dented</i>	1	\$ 1,965.89	\$ 1,965.89
11	REAR BUMPER SIDE RETAINER <i>RH Dmgd</i>	2	\$ 65.90	\$ 131.80
12	REAR BUMPER BRACKET <i>RH cruld</i>	2	\$ 89.40	\$ 178.80
13	REAR BUIMPER REFLECTOR <i>RH cruld</i>	2	\$ 95.40	\$ 190.80
14	TAIL LAMP <i>RH cruld</i>	2	\$ 485.40	\$ 970.80
15	TAIL LAMP LOWER BRACKET <i>new</i>	2	\$ 89.50	\$ 179.00
16	TAIL LAMP PANEL <i>RHS</i>	2	\$ 280.30	\$ 560.60
17	REAR END PANEL <i>Dented</i>	1	\$ 630.00	\$ 630.00
18	REAR END PANEL TOP GARNISH <i>cruld</i>	1	\$ 191.50	\$ 191.50

4457.40
3343.05

TOTAL PRICE \$ 7,651.44
LESS 25% \$ 1,912.86
SUB TOTAL PRICE \$ 5,738.58

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Dented.</i>	1	\$ 50.00	\$ 50.00 ✓
2	BOOT LID MOULDING CLIP(SET) <i>New</i>	1	\$ 50.00	\$ 50.00 10
3	REAR BUMPER CLIP(SET) <i>New</i>	1	\$ 50.00	\$ 50.00 30
4	TAILLAMP PANEL SEALANT <i>New New</i>	2	\$ 150.00	\$ 300.00 X
5	TAIL LAMP CLIP(SET) <i>New</i>	1	\$ 50.00	\$ 50.00 10
6	REAR END PANEL INSULATION SEAL <i>New</i>	1	\$ 150.00	\$ 150.00 60
7	REAR END PANEL TOP GARNISH CLIP(SET) <i>New</i>	1	\$ 50.00	\$ 50.00 20
8	REAR REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00 200

380

TOTAL \$ 920.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	TO PANEL BEAT, WELD, CUT, KNOCK STRAIGHTEN, ADJUST GRAZE, JOIN	\$ 1,600.00	800	
2	TO PUTTY, SPRAY PAINT, POLISH, WAX AFFECTED PARTS AND PANELS	\$ 1,600.00	800	
3	TUFF COAT	\$ 300.00	60	
4	WIRING CHECK	\$ 180.00	30	
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 250.00	60	
6	TRANFER BOOTLID MECHANISM	\$ 180.00	60	
7	CONDUCT WATER LEAKAGE TEST	\$ 180.00	X	
8	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 180.00	50	
9	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 180.00	50	

TOTAL

\$4,650.00

1910

ESTIMATE REPORT

TOTAL PARTS COST : \$ 6,658.58

TOTAL LABOUR COST : \$ 4,650.00

TOTAL REPAIR COST : \$ 11,308.58

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

Adrian King.
h/s 19/04/21.
06 Days.

total: 5633.05
h/s: A.SK

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: