

MFORTDELGRO ENGINEERING PTE LTD.

PAIR ESTIMATE*

VEHICLE NO SHC8551M

6/04/2021

MAKE

MODEL HYU- I40

CHIANG /LONPAC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$1,106.00
2	REAR BUMPER BRACKET SIDE LH /RH		\$35.60	\$71.20
10	REAR BUMPER CLIPS		\$2.20	\$22.00
1	REAR BUMPER UNDER COVER			\$228.00
1	REAR BUMPER REINFORCEMENT			\$394.80
1	REAR PANEL GARNISH			\$57.50
1	REAR END PANEL			\$526.70
1	REAR PANEL LOWER			\$495.50
2	REAR BUMPER REFLECTOR LH/RH		\$32.00	\$64.00
				\$2,965.70
			1160	\$593.14
			928	\$2,372.56
	20.00% DISCOUNTED TOTAL			
1	REAR BUMPER ADVERTISEMENT			\$50.00
1	REVERSE SENSOR 10%			\$135.70
			172-13	\$185.70
	Labour Charge			
	Panel Beating			\$600.00
	Spray Painting Charge			\$600.00
	Check lighting			\$50.00
	Remove/refix reverse sensor			\$60.00
	Tuff Kote			\$60.00
	TOTAL LABOUR			\$1,370.00
	ESTIMATE TOTAL			\$3,928.26
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Taylor 97495747
WP 19/4/21 @ 440.
2 days
4/3 Running after repair
Taylor @ Wharfedale.