



S THREE AUTOMOTIVE RECOVERY PTE LTD

Not Notion
L1 Rep @ 12,400k
Bunny Ate Rain

TO :
ATTN : MOTOR CLAIM DEPT.

T/P VEH. NO.: SLZ3228L

ESTIMATE REPORT 1st QUOTATION

JOB NO: _____

OWNER'S PARTICULAR

CONTACT: _____

NAME: MALARVILI THYAGARAJAN

ADDRESS: _____

LICENSE NO.: SGJ7277L TRANS.

CHASSIS NO: _____

MAKE / MODEL: MERCEDES C180

ENGINE NO: _____

OWNER'S INSURER: AIG INSURANCE

ACCIDENT DATE: 18-Mar-21

JOB-CODE: TP S/A: MICHELLE

CLAIM DETAIL

MATERIALS

	QTY	QUO-PRICE	DISC. %	DISC-PRICE	SUR. DISP	EV. PRIC
1 FRONT BUMPER 1651	Bu 1.00	\$ 1,810.00	10.00	\$ 1,629.00	Y	✓
2 FRONT BUMPER SPONGE 132	cm 1.00	\$ 164.00	10.00	\$ 147.60	Y	✓
3 FRONT BUMPER REINFORCEMENT	R 1.00	\$ 520.00	10.00	\$ 468.00	Y	X
4 FRONT BUMPER RETAINER RH&LH 068	Di 2.00	\$ 190.00	10.00	\$ 171.00	Y	✓
5 FRONT BUMPER BRACKET RH&LH 090	R 2.00	\$ 210.00	10.00	\$ 189.00	Y	X
6 FRONT BUMPER INNER PLASTIC BEAM 167	cm 1.00	\$ 185.00	10.00	\$ 166.50	Y	✓
7 FRONT BUMPER CENTRE GRILLE	su 1.00	\$ 327.00	10.00	\$ 294.30	Y	X
8 FRONT BUMPER LOWER CHROME MOULDING	su 1.00	\$ 184.00	10.00	\$ 165.60	Y	X
9 FRONT BUMPER SENSOR 1SET	shot 2 1.00	\$ 672.00	10.00	\$ 604.80	Y	24+336
10 FRONT BUMPER SENSOR HOLDER	mu 4.00	\$ 160.00	10.00	\$ 144.00	Y	✓
11 FRONT BUMPER SENSOR WIRE HARNESS	su 1.00	\$ 182.00	10.00	\$ 163.80	Y	X
12 FRONT BUMPER SEAL	re 1.00	\$ 80.00	10.00	\$ 72.00	Y	X
13 FRONT BUMPER HOLDER BRACKET LH	Di 1.00	\$ 60.00	10.00	\$ 54.00	Y	✓
14 FRONT BUMPER HOLDER BRACKET RH	Di 1.00	\$ 60.00	10.00	\$ 54.00	Y	✓
15 FRONT BUMPER LOWER COVER	Re 1.00	\$ 220.00	10.00	\$ 198.00	Y	✓
16 FRONT RADAR SENSOR	su 1.00	\$ 680.00	10.00	\$ 612.00	Y	X
17 FRONT FENDER LH	R 1.00	\$ 1,410.00	10.00	\$ 1,269.00	Y	X
18 FRONT FENDER RH	R 1.00	\$ 1,410.00	10.00	\$ 1,269.00	Y	X
19 HEADLAMP LED LH 3280-40	m/cm 1.00	\$ 3,332.00	10.00	\$ 2,998.80	Y	X
20 HEADLAMP LED RH 3280-40	7 1.00	\$ 3,332.00	10.00	\$ 2,998.80	Y	✓
21 HEADLAMP PANEL LH	R 1.00	\$ 250.00	10.00	\$ 225.00	Y	X
22 HEADLAMP PANEL RH	bent 1.00	\$ 250.00	10.00	\$ 225.00	Y	X
23 FRONT GRILLE	cm 1.00	\$ 275.00	10.00	\$ 247.50	Y	✓
24 FRONT GRILLE LOGO	mu 1.00	\$ 128.00	10.00	\$ 115.20	Y	✓
25 FRONT GRILLE CHROME MOULDING 4PCS	ad 2 1.00	\$ 280.00	10.00	\$ 252.00	Y	✓
26 FRONT GRILLE INNER HOLDER PLASTIC	cm 1.00	\$ 252.00	10.00	\$ 226.80	Y	✓
27 FRONT GRILLE COVER OUTER 285	cm 1.00	\$ 337.00	10.00	\$ 303.30	Y	✓
28 SUPPORT PANEL TOP CENTRE	R 1.00	\$ 268.00	10.00	\$ 241.20	Y	X
29 REAR BUMPER 1831	m/cm 1.00	\$ 1,865.00	10.00	\$ 1,678.50	Y	✓
30 REAR BUMPER REINFORCEMENT	R 1.00	\$ 680.00	10.00	\$ 612.00	Y	X

Aspire 3

A314-32-C6Z5

DDR4

1	REAR BUMPER SPONGE	1.00	\$	138.00	10.00	\$	124.20	Y	X
32	REAR BUMPER INNER REINFORCEMENT PLASTIC 180	1.00	\$	320.00	10.00	\$	288.00	Y	X
33	REAR BUMPER TOWING COVER	1.00	\$	120.00	10.00	\$	108.00	Y	X
34	REAR BUMPER LOWER LID 270	1.00	\$	365.00	10.00	\$	328.50	Y	X
35	REAR BUMPER SIDE RETAINERS LH	1.00	\$	80.00	10.00	\$	72.00	Y	X
36	REAR BUMPER SIDE RETAINERS RH	1.00	\$	80.00	10.00	\$	72.00	Y	X
37	REAR BUMPER LOWER BRACKET LH 165	1.00	\$	238.00	10.00	\$	214.20	Y	X
38	REAR BUMPER LOWER BRACKET RH 165	1.00	\$	238.00	10.00	\$	214.20	Y	X
39	REAR BUMPER CHROME CENTRE 215	1.00	\$	380.00	10.00	\$	342.00	Y	X
40	REAR BUMPER REINFORCEMENT BRACKET	1.00	\$	178.00	10.00	\$	160.20	Y	X
41	REAR BUMPER INNER SIDE GARNISH LH	1.00	\$	238.00	10.00	\$	214.20	Y	X
42	REAR BUMPER INNER SIDE GARNISH RH	1.00	\$	238.00	10.00	\$	214.20	Y	X
43	TAILLAMP RH	1.00	\$	920.00	10.00	\$	828.00	Y	X
44	TAILLAMP LH	1.00	\$	920.00	10.00	\$	828.00	Y	X
45	BOOTLID EMBLEM LOGO	1.00	\$	62.00	10.00	\$	55.80	Y	X
46	BOOTLID EMBLEM C180	1.00	\$	68.00	10.00	\$	61.20	Y	X
47	BOOTLID EMBLEM CC	1.00	\$	68.00	10.00	\$	61.20	Y	X
48	REAR END PANEL OUTER	1.00	\$	770.00	10.00	\$	693.00	Y	X
49	REAR END PANEL INNER GARNISH	1.00	\$	216.00	10.00	\$	194.40	Y	X
50	REAR EXHAUST SILENCER ASSEMBLY	1.00	\$	1,980.00	10.00	\$	1,782.00	Y	X
51	REAR EXHAUST MOUNTINGS	1.00	\$	95.00	10.00	\$	85.50	Y	X
52	REAR EXHAUST CHROME	1.00	\$	398.00	10.00	\$	358.20	Y	X
53	REVERSE SENSOR 1SET 2330	1.00	\$	1,200.00	10.00	\$	1,080.00	Y	X
54	KICK BOOT SENSOR (AUTO SENSOR) 485	1.00	\$	580.00	10.00	\$	522.00	Y	X
55	REAR BUMPER TOP SUPPROT BRACKET RH 95	1.00	\$	168.00	10.00	\$	151.20	Y	X
56	REAR BUMPER TOP SUPPORT BRACKET LH 95	1.00	\$	168.00	10.00	\$	151.20	Y	X
TOTAL (PARTS):				29999.00			26999.10		

SPECIAL NETT ITEM

1	FRONT BUMPER CLIPS	1.00	\$	50.00	0.00	\$	50.00	Y	X
2	FRONT BUMPER LOWER COVER CLIPS	1.00	\$	50.00	0.00	\$	50.00	Y	X
3	FRONT FENDER INNER SHIELD CLIPS LH	1.00	\$	50.00	0.00	\$	50.00	Y	X
4	FRONT FENDER INNER SHIELD CLIPS RH	1.00	\$	50.00	0.00	\$	50.00	Y	X
5	FRONT NO. PLATE WITH GARNISH	1.00	\$	150.00	0.00	\$	150.00	Y	X
6	FRONT GRILLE CLIPS	1.00	\$	50.00	0.00	\$	50.00	Y	X
7	FRONT SUPPER PANEL CLIPS	1.00	\$	50.00	0.00	\$	50.00	Y	X
8	REAR BUMPER CLIPS	1.00	\$	50.00	0.00	\$	50.00	Y	X
9	REAR BUMPER LOWER SPOILER	1.00	\$	680.00	0.00	\$	680.00	Y	X
10	TAILLAMP SIDE GARNISH CLIPS (1SET)	1.00	\$	100.00	0.00	\$	100.00	Y	X
11	REAR END PANEL INNER GARNISH CLIPS	1.00	\$	50.00	0.00	\$	50.00	Y	X
12	REAR END PANEL SEALANT	1.00	\$	80.00	0.00	\$	80.00	Y	X
TOTAL (PARTS):				1410.00			1410.00		

LABOUR

1	STRAIGHTEN & PANEL BEAT ACCIDENT AREA - FRONT	1.00	\$	1,500.00	0.00	\$	1,500.00	Y	500
---	---	------	----	----------	------	----	----------	---	-----

STRAIGHTEN & PANEL BEAT ACCIDENT AREA - REAR	1.00	\$	1,500.00	0.00	\$	1,500.00	Y	300d
SPRAY PAINTING ON ACCIDENT AREA - FRONT	1.00	\$	1,600.00	0.00	\$	1,600.00	Y	500d
4 SPRAY PAINTING ON ACCIDENT AREA - REAR	1.00	\$	1,600.00	0.00	\$	1,600.00	Y	250d
5 CHECK & REPAIR WIRING SYSTEM	1.00	\$	120.00	0.00	\$	120.00	Y	40d
RESET HEADLAMP LED & CALIBRATE SYSTEM	1.00	\$	300.00	0.00	\$	300.00	Y	120d
R&R REAR REVERSE SENSOR & RESETTNG SYSTEM	1.00	\$	300.00	0.00	\$	300.00	Y	120d
RESPRAY TUFF KOTE ON ACCIDENT AREA	1.00	\$	120.00	0.00	\$	120.00	Y	X
R&R BOOTLID INNER FITTINGS	1.00	\$	120.00	0.00	\$	120.00	Y	X

TOTAL (LABOUR):

7160.00

7160.00

TOTAL PARTS & LABOUR

38569.00

35569.10

CESS: : S\$

OF DAY : 05 days

SURVEY: BEFORE / AFTER PAINTING

RT BY-PART OR LUMP-SUM : S\$

TE OF SURVEY : 19/4/21

RVEY BY : Kenneth

NTACT NO :

FAX NO :

TE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.