



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Ref: CS3/CTI21000205/Gtf3n2-1	
			Date: 07/05/2021	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	SMD 8197M	Veh. Inspected	SKP 6613C	
Policy No.	DMPCSNW00067202000	Coverage (\$)	0.00	
Claim No.	SNM21D200055/C02	Excess (\$)	0.00	
Assign From	JENNY LEW	Assign Date	19/04/2021	
2. Vehicle Particulars & Condition				
Make & Model	BMW 520I	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	WBA5A32060D789326	Colour	BLACK	
Odometer	114573 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/35 ZR20	MICHELIN	6 mm	
L/H Front Tyre	245/35 ZR20	MICHELIN	6 mm	
R/H Rear Tyre	245/35 ZR20	MICHELIN	6 mm	
L/H Rear Tyre	245/35 ZR20	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.				
REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	31/12/2020	Inspection Date	20/04/2021	
Survey held at	38 WOODLANDS INDUSTRIAL PARK E1. #04-14			
Repairer	TEC AUTO SERVICES PTE LTD			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.				
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			10 Working Days	