

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

16-Apr-21

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6985 H

1 pc	Bootlid emblem	\$	27.00	X
1 pc	Bootlid CRDi	\$	29.00	X
1 pc	Boot lid lower garnish	\$	290.00	X
1 pc	Rear bumper	\$	696.00	de
1 pc	Rear bumper lower cover	\$	206.00	Rp
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	d/s \$	58.00	n/s
1 pc	Rear bumper inner sponge	\$	114.00	X
1 pc	Rear bumper reinforcement	\$	607.00	X
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	d/s \$	108.00	n/s
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$	36.00	X
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$	36.00	X
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00	d/s \$	92.00	n/s
1 pc	n/s tail lamp @\$421.00	\$	421.00	ent
1 pc	n/s reflector @\$350.00	\$	350.00	X n/s
		\$	3,070.00	
	Less 10%	\$	307.00	
		\$	2,763.00	

1117

10/1005.30

### S/NETT

1 set	Rear bumper clips	\$	48.00	30 nec
1 set	Bootlid lower garnish clips	\$	60.00	X
1 set	Bootlid stickers	\$	100.00	X
1 set	Rear n/s fender inner shield clips	\$	28.00	X
1 set	Reverse sensor	\$	280.00	200 X
1 pc	Rear bumper top protector	\$	80.00	nc
1 pc	Rear no. plate with casing	\$	50.00	X n/s

110

16-Apr-21

# ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6985 H

1 pc

Sealant

\$ 50.00 X un

Sundry

\$ 50.00 X un

To dismantle / replace reverse sensor to new bumper and reset to the same

\$ 120.00 30

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

\$ 180.00 X un

To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel, floorboard panel, rear n/s & o/s fenders. Including knock-out, straighten, repair, reshape and adjust of the rear panel

200

\$800.00

To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, end panel,

\$ 800.00 200

To apply rustproofing on the repaired and replaced panels.

\$ 150.00 X un

\$ 5,559.00

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

430

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

1545.30

4581200

2 days

Tanpin 97495749  
'WP' 19/4/21 2330pm  
2 days  
i/s Resurvey after repair

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: