

# SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SMR2248R/2103022

23<sup>th</sup> April 2021

The Manager  
Motor Claim Department  
MSIG Insurance (Singapore) Pte Ltd  
16 Raffles Quay  
#24-01 Hong Leong Building  
Singapore 048581

Date of Accident : 10<sup>th</sup> February 2021  
Location : Keppel Rd Towards West Coast

Third Party Claim Vehicle No : FBC 1412 Z  
Repair Cost For Vehicle No : SMR 2248 R

## Estimated Cost Plus/ Supply of Parts & Labours

| No. | Particulars                                                   | Qty  | Price                  | Amounts                      |
|-----|---------------------------------------------------------------|------|------------------------|------------------------------|
| 1   | ✓ Front bonnet <i>DO/SUC 3647.40</i>                          | 1    | 3,952.00               | \$ 3,952.00 ✓                |
| 2   | Front bonnet insulation shield <i>11</i>                      | 1    | 855.00                 | \$ 855.00 X                  |
| 3   | ✓ Front bonnet insulation clips <i>nee 90</i>                 | 1set | 114.00                 | \$ 114.00 ✓                  |
| 4   | Front bonnet lock LH <i>11</i>                                | 1    | 256.5                  | \$ 256.50 X                  |
| 5   | ✓ Front bumper fascia <i>Dis 2054</i>                         | 1    | 3,173.00               | \$ 3,173.00 ✓                |
| 6   | ✓ Front bumper clips <i>nee 68</i>                            | 1set | 90.00                  | \$ 90.00 ✓                   |
| 7   | Front bumper side retainer L&R <i>11</i>                      | 2    | 102.60                 | \$ 205.20 X                  |
| 8   | ✓ Headlamp L&R <i>one 1862.40 LH RH 2191.30</i>               | 2    | 3,325.00 <del>12</del> | \$ 3,500.00 ✓ <i>4053.70</i> |
| 9   | Headlamp bracket LH <i>11</i>                                 | 1    | 180.50                 | \$ 180.50 X                  |
| 10  | ✓ Headlamp washer cover LH <i>mis</i>                         | 1    | 47.50                  | \$ 47.50 ✓                   |
| 11  | Headlamp washer nozzle jet LH <i>11</i>                       | 1    | 209.00                 | \$ 209.00 X                  |
| 12  | ✓ Front grille base <i>one 825.80</i>                         | 1    | 988.00                 | \$ 988.00 ✓                  |
| 13  | Front grille chrome <i>&gt; complete</i>                      | 1    | 969.00                 | \$ 969.00 X                  |
| 14  | Front grille emblem                                           | 1    | 102.60                 | \$ 102.60 X                  |
| 15  | ✓ Front bumper lower grille <i>70.11</i>                      | 1    | 152.00                 | \$ 152.00 ✓                  |
| 16  | ✓ Front fog lamp garnish L&R <i>bumper 70.11/mis 93x2=186</i> | 2    | 114.00                 | \$ 228.00 ✓                  |
| 17  | ✓ Front bumper diffuser <i>lower cover Dis</i>                | 1    | 171.00                 | \$ 171.00 ✓                  |
| 18  | Front fender LH <i>R</i>                                      | 1    | 1,482.00               | \$ 1,482.00 X                |
| 19  | Front fender cowling LH <i>11</i>                             | 1    | 285.00                 | \$ 285.00 X                  |
| 20  | Front fender cowling LH clips <i>11</i>                       | 1set | 95.00                  | \$ 95.00 X                   |
| 21  | ✓ Front support panel <i>Bent/1m 1433.90</i>                  | 1    | 1,862.00               | \$ 1,862.00 ✓                |
| 22  | ✓ Front bumper lower cover <i>inner one 472.90</i>            | 1    | 627.00                 | \$ 627.00 ✓                  |
| 23  | Front fog lamp LH <i>11</i>                                   | 1    | 608.00                 | \$ 608.00 X                  |
|     |                                                               |      |                        | \$ 20,152.30                 |

13202-2

# SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SMR2248R/2103022

23<sup>th</sup> April 2021

| No.  | Particulars                               | Qty              | Price             | Amounts              |
|------|-------------------------------------------|------------------|-------------------|----------------------|
|      | Balance b/f                               |                  |                   | \$ 20,152.30         |
| 24 ✓ | Intercooler <i>put</i>                    | 1                | 1,026.00          | \$ 1,026.00          |
| 25 ✓ | Air guide LH(top) <i>70.20</i>            | 1                | <del>64.60</del>  | \$ <del>64.60</del>  |
| 26 ✓ | Air guide LH(lower) <i>70.20</i>          | 1                | 79.80             | \$ 79.80             |
| 27 ✓ | Horn LH <i>ena</i>                        | 1                | 125.40            | \$ 125.40            |
| 28   | Front fender cowling RH <i>11</i>         | 1                | 304.00            | \$ 304.00 X          |
| 29 ✓ | Cross member <i>buy</i>                   | 1                | 494.00            | \$ 494.00            |
| 30 ✓ | Front bumper support <i>buy</i>           | 1                | <del>209.00</del> | \$ <del>209.00</del> |
| 31 ✓ | Front fender cowling screw <i>11</i>      | 1 set            | 100.00            | \$ 100.00 X          |
| 32 ✓ | Washer tank <i>de</i>                     | 1                | 110.20            | \$ 110.20            |
| 33 ✓ | Front bumper lower cover clips <i>new</i> | 5.70 X 3 = 17.10 | 6.00              | \$ 18.00 17.10       |
|      |                                           |                  |                   | \$ 22,683.30         |

## Labour Charges :-

|                                                                                                                                                      | Amounts                  |
|------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|
| Cut out, renew, knocking & welding front bonnet, front support panel, front fender LH, remove & install all damage parts, straighten & re-align body | \$ 1,380.00 <i>850</i>   |
| Tuff-kote on damage parts                                                                                                                            | \$ 120.00 <i>50</i>      |
| Spray painting on damage parts                                                                                                                       | \$ 1,880.00 <i>900</i>   |
| Check all lighting after repairs                                                                                                                     | \$ 60.00 <i>30</i>       |
| Labour Charge                                                                                                                                        | \$ 3,440.00              |
| Total Amount                                                                                                                                         | \$ 26,123.30 <i>1830</i> |

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*P. 17412.70*  
*52*  
*16542.06*  
*50*  
*1830*  
*18422.06*