



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2108241

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 29/11/2021
Reference CC6/CTI21004878/Aea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. YN 9372Y
Insured Veh. XE 3606Y
Claim No. SNM21D202143/C02
Policy No. DMCVSNA00093262003
Accident Date 13/04/2021
Inspection Date 16/04/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21004878/Aea3q2	
			Date: 29/11/2021	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XE 3606Y		Veh. Inspected	YN 9372Y
Policy No.	DMCVSNA00093262003		Coverage (\$)	0.00
Claim No.	SNM21D202143/C02		Excess (\$)	0.00
Assign From			Assign Date	16/04/2021
2. Vehicle Particulars & Condition				
Make & Model	HINO XZU710R		c.c	4009
Engine No.	HIDDEN		Year of Reg.	2015
Chassis No.	JHHUCT3HX0K014338		Colour	WHITE
Odometer	126466 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	NIL
General	GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
R/H Front Tyre		215/85 R16	KENDA	6 mm
L/H Front Tyre		215/85 R16	KENDA	6 mm
R/H Rear Tyre		215/85 R16	KENDA	6 mm
L/H Rear Tyre		215/85 R16	KENDA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	13/04/2021		Inspection Date	16/04/2021
Survey held at	XIN HUA WORKSHOP PTE LTD 23 KAKI BUKIT AVENUE 4 #04-01 (SOUTH WING) SINGAPORE 415933			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		18 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 9372Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT PANEL	DENTED	1,689.80	1,250.00
1	FRONT INNER PANEL	TO REPAIR SEE LABOUR	1,345.60	-
2	FRONT WIPER BAR @\$345.90	BENT	691.80	345.90
1	FRONT PANEL STICKER (HINO)	NECESSARY	189.20	95.00
1	FRONT PANEL STICKER (300)	NECESSARY	189.50	85.00
2	FRONT CORNER PANELS @\$386.80	CRACKED	773.60	773.60
2	SET FRONT CORNER PANELS CLIPS @\$40.00	NECESSARY	80.00	40.00
1	FRONT GRILLE	CRACKED	825.70	684.00
1	FRONT GRILLE BADGE	NECESSARY	95.00	95.00
1	SET FRONT GRILLE CLIPS	NECESSARY	30.00	30.00
1	FRONT BUMPER	DISTORTED	1,286.70	973.00
1	FRONT BUMPER REINFORCEMENT	BENT	698.80	345.00
1	FRONT BUMPER TOWING HOOD	NOT NECESSARY	195.00	-
2	FRONT BUMPER FOG LAMP @\$198.70	NOT NECESSARY	397.40	-
2	HEADLAMPS @\$1235.80	CRACKED	2,471.60	1,821.00
2	SET HEADLAMPS CLIPS @\$40.00	NECESSARY	80.00	20.00
2	BRAKE OIL PIPE @\$136.00	BENT	272.00	272.00
1	CLUTCH OIL PIPE	BENT	162.00	162.00
1	SET HORNS	NOT NECESSARY	120.00	-
1	AIR CON CONDENSER	NOT NECESSARY	1,295.00	-
1	SET CONDENSER FAN COWLING /FAN MOTOR /FAN BLADE ASSY	NOT NECESSARY	890.00	-
1	CONDENSER AIR CON PIPE	BENT	352.00	352.00
1	CONDENSER SUCTION PIPE	BENT	346.00	346.00
1	CONDENSER DISCHARGE PIPE	BENT	342.00	342.00
1	FRONT DOOR PILLAR RH	TO REPAIR SEE LABOUR	1,750.00	-
1	FRONT CABIN ROLLER BAR	TO REPAIR SEE LABOUR	1,256.80	-
1	SIDE AIR INTAKE VENT RH	DEFORMED	398.70	398.70
1	AIR CLEANER BOX	NOT NECESSARY	865.90	-

Report Ref No. CC6/CTI21004878/Aea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT FUSE BOX	NOT NECESSARY	485.80	-
2	FRONT FENDER ARCH COVER @\$345.80	O/S TORN	691.60	345.80
1	FRONT BLOWER MOTOR WITH COVER	CRACKED	1,876.50	1,876.50
1	AIR ASSY ,AIR DAMPER	NOT NECESSARY	456.90	-
1	FRONT DASHBOARD	CRACKED	923.80	923.80
2	FRONT STEP PANEL GARNISH @\$308.90	CRACKED	617.80	617.80
1	FRONT WASHER TANK	CRACKED	245.30	245.30
1	FRONT WINDSCREEN INNER SEAL	NECESSARY	186.90	186.90
1	FRONT BUMPER BRACKET	BENT	387.90	387.90
	LESS 10% DISCOUNT		-2,496.26	-1,301.42
			22,466.34	11,712.78
	<u>SPECIAL NETT ITEMS</u>			
2	TAILLAMPS @\$356.80 (SN)	NOT NECESSARY	713.60	-
2	NUMBER PLATE (FRONT AND REAR) @\$50.00 (SN)	BENT	100.00	60.00
1	NUMBER PLATE BASE (SN)	BENT	220.00	80.00
1	NUMBER PLATE LAMP (SN)	NOT NECESSARY	85.00	-
1	REAR NUMBER PLATE WIRING HARDESS (SN)	NOT NECESSARY	345.80	-
1	REAR WOODEN TAILGATE (SN)	CRACKED	2,000.00	1,700.00
4	REAR WOODEN TAILGATE METAL BAR @\$200.00 (SN)	BENT	800.00	500.00
1	REAR WOODEN TAILGATE STICKER 60KM (SN)	NECESSARY	20.00	15.00
4	REAR WOODEN TAILGATE HINGES @\$150.00 (SN)	BENT	600.00	320.00
1	REAR LOWER METAL MEMBER FRAME (SN)	DISTORTED	3,800.00	800.00
1	REAR TAILGATE LOWER WOODEN MEMBER (SN)	CRACKED	1,300.00	800.00
1	REAR REINFORCEMENT BAR (SN)	BENT	1,200.00	800.00
2	REAR REINFORCEMENT BAR BRACKETS @\$450.00 (SN)	BENT	900.00	500.00
1	REAR CHASSIS CROSS MEMBER (SN)	TO REPAIR SEE LABOUR	2,000.00	-
1	REAR WOODEN STEP BAR (SN)	CRACKED	550.00	350.00
2	MAIN WOODEN MEMBER @\$2200.00 (SN)	CRACKED	4,400.00	2,600.00
6	MAIN WOODEN MEMBER U CLAMP @\$180.00(SN)	BENT	1,080.00	300.00
19	REAR TOP WOODEN FLOOR BOARD @\$800.00 (SN)	CRACKED	15,200.00	2,500.00
7	REAR WOODEN HORIZONTAL MEMBER @\$800.00 (SN)	CRACKED	5,600.00	2,200.00
4	REAR SIDE WOODEN TAILGATE @\$180.00 (SN)	NOT NECESSARY	7,200.00	-

Report Ref No. CC6/CTI21004878/Aea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
12	REAR SIDE WOODEN TAILGATE HINGES @\$150.00 (SN)	NOT NECESSARY	1,800.00	-
12	SIDE METAL BAR PLATE @\$200.00 (SN)	NOT NECESSARY	2,400.00	-
4	REAR TAILGATE SIDE LATCH LOCK @\$250.00 (SN)	DAMAGED	1,000.00	300.00
2	CENTRE SIDE PANEL LOCK @\$180.00 (SN)	NOT NECESSARY	360.00	-
2	REAR WHEEL ARCH COVER @\$380.00 (SN)	NOT NECESSARY	760.00	-
4	REAR WHEEL ARCH COVER SUPPORT BAR @\$180.00 (SN)	NOT NECESSARY	720.00	-
2	REAR MUDFLAPS @\$280.00 (SN)	NOT NECESSARY	560.00	-
2	SIDE BOTTOM REINFORCEMENT BAR @\$1200.00 (SN)	NOT NECESSARY	2,400.00	-
1	FRONT WOODEN HORIZONTAL MEMBER (SN)	CRACKED	1,300.00	700.00
1	FRONT WOODEN CENTRE SUPPORT (SN)	NOT NECESSARY	950.00	-
2	FRONT WINDSCREEN SEALANT @\$40.00 (SN)	NECESSARY	80.00	80.00
1	SET COMPANY STICKER (SN)	NOT NECESSARY	900.00	-
			61,344.40	14,605.00
	LABOUR			
	TO RENEW DAMAGED PARTS ,REPLACE ,BEAT ,WELD AND ALIGN ALL PARTS.INCLUSIVE OF THE REPAIR OF REAR CHASSIS CROSS MEMBER ,FRONT INNER PANEL ,FRONT DOOR PILLAR RH AND FRONT CABIN ROLLER BAR.		3,800.00	1,200.00
	TO RESPRAY AFFECTED AREAS .		3,000.00	1,500.00
	TO APPLY UNDERCOATING TO THE AFFECTED AREAS .		450.00	250.00
	LABOUR TO CHECK WIRING FOR TAILAMPS AND REVERSE LAMPS.		200.00	60.00
	LABOUR TO DISMANTLE AND LIFT WOODEN BODY TO CARRY OUT REPAIR .		1,200.00	800.00
	LABOUR TO REMOVE AND INSTALL FRONT DASHBOARD .		500.00	280.00
	TO REMOVE CONDENSER AND TOP UP AIR CON GAS .	NOT NECESSARY	120.00	-
	TO PERFORM HEADLAMP FOCUSING.	NOT NECESSARY	150.00	-
	TO REMOVE /REFIT FRONT WINDSCREEN FOR FRONT PANEL REPLACEMENT .		120.00	120.00
	TO REALIGN ,ASSEMBLR REAR WOODEN BODY AND METAL FRAME .		1,200.00	800.00
			10,740.00	5,010.00
	GRAND TOTAL		94,550.74	31,327.78

Report Ref No. CC6/CTI21004878/Aea3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			25,000.00
---	--	--	------------------

Report Ref No. CC6/CTI21004878/Aea3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. YN 9372Y

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. YN 9372Y

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. YN 9372Y

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. YN 9372Y

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

