

Section A - Accident Details

|                                    |                                    |
|------------------------------------|------------------------------------|
| Registration Number                | SHB1235C                           |
| Case Reference Number              | TAX/04/21/2050                     |
| Registration Date                  | 28/11/2017                         |
| Company Type                       | SMRT Taxis Pte Ltd                 |
| Make                               | TOYOTA                             |
| Model                              | PRIUS4                             |
| Name of Driver                     | HOONG KENG HENG                    |
| Type of Accident                   | Side Swipe                         |
| Accident Date and Time             | 18/4/2021 1:20 PM                  |
| Accident Reported Date and Time    | 19/4/2021 9:27 AM                  |
| Is Surveyor Required?              | Yes                                |
| Survey by                          |                                    |
| Vehicle is Towed Back?             | No                                 |
| Towed Back Date and Time           |                                    |
| Replacement Vehicle issued?        | No                                 |
| Job Card Number                    | 24110576                           |
| Special Instruction to ARC, if any | TP/ DROVE IN / RIGHT FRONT PORTION |
| Prepared Date and Time             | 19/4/2021 12:39 PM                 |
| Chassis Number                     |                                    |
| Mileage                            |                                    |
| Work Shop                          |                                    |
| Repair Completion Date and Time    |                                    |

Section B - Summary of Repair Estimates

Summary of Repair Estimates

|                              | Quotation from ARC                                                                  | Adjusted by Surveyor, if applicable                                                                                                                               |
|------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Total Labour Cost            | \$876.00                                                                            | \$350.00                                                                                                                                                          |
| Total Spray Cost             | \$2,610.00                                                                          | \$600.00                                                                                                                                                          |
| Total Spare Part Cost        | \$16,202.05                                                                         | \$4,541.91                                                                                                                                                        |
| Total Other Cost             | \$720.00                                                                            | \$80.00                                                                                                                                                           |
| <b>TOTAL COST</b>            | <b>\$20,408.05</b>                                                                  | <b>\$5,571.91</b>                                                                                                                                                 |
| <b>Lump Sum Total</b>        | <b>\$20,400.00</b>                                                                  | <b>\$5,550.00 (L/S)</b>                                                                                                                                           |
| Number of Repair Days        | 6.0                                                                                 | 3.0                                                                                                                                                               |
| Prepared / Adjusted By       | Ang Bang Kien                                                                       | Kenneth Kong (LKK) / Sompo                                                                                                                                        |
| ARC / Surveyor Sign Off Date | 22/04/2021 2:55 PM                                                                  | 22/04/2021 11:07 AM                                                                                                                                               |
| Signature                    |  |                                                                                |
| Remarks                      | Total number of repair days = 3 days.<br>SUP = 0 day.                               | Lump Sum repair, resurvey after paint. \ FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR Kenneth Kong (LKK) HP : 9691 0663 / Email : kennethkong@lkkauto.com |

**Section C - Quotation and Accident Invoice Details**

|                  |              |                |  |
|------------------|--------------|----------------|--|
| Quotation Number | QN-2105-0052 | Invoice Number |  |
| Quotation Date   | 06.05.2021   | Invoice Date   |  |
| Invoice Amount   |              | Prepared Date  |  |

**Section D - Details of Repair Estimates**
**Part 1 - Labour Works**

| Job Scope                  | Quotation from AR | Adjusted by Surveyor, if applicable |
|----------------------------|-------------------|-------------------------------------|
| TO REPAIR FRONT RH PORTION | \$676.00          | \$350.00                            |
| TO REPAIR FRONT HOOD       | \$200.00          | \$0.00                              |
| <b>Total Labour</b>        | <b>\$876.00</b>   | <b>\$350.00</b>                     |

**Part 2 - Spray Painting & Panel Beating Related Works**

| Job Scope                                       | Quotation from ARC | Adjusted by Surveyor, if applicable |
|-------------------------------------------------|--------------------|-------------------------------------|
| TO REPSRAY FRONT HOOD                           | \$378.00           | \$0.00                              |
| TO REPSRAY FRONT HOOD                           | \$378.00           | \$0.00                              |
| TO REPSRAY FRONT BUMPER                         | \$378.00           | \$200.00                            |
| TO RESPRAY FRONT BUMPER LOWER GRILLE            | \$180.00           | \$0.00                              |
| TO RESPRAY FRONT FENDER RH                      | \$378.00           | \$200.00                            |
| TO RESPRAY FRONT DOOR RH                        | \$378.00           | \$200.00                            |
| RESPRAY MIRROR COVER RH                         | \$180.00           | \$0.00                              |
| TO RESPRAY RIM                                  | \$180.00           | \$0.00                              |
| TO RESPRAY FRONT SUPPORT PANEL                  | \$180.00           | \$0.00                              |
| <b>Total Spray Painting &amp; Panel Beating</b> | <b>\$2,610.00</b>  | <b>\$600.00</b>                     |

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

| Job Scope                                       | Quotation from ARC | Adjusted by Surveyor, if applicable |
|-------------------------------------------------|--------------------|-------------------------------------|
| TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE) | \$120.00           | \$0.00                              |
| TO DO WHEEL ALIGNMENT / TYRE BALANCING          | \$120.00           | \$60.00                             |
| TO REMOVE AND REFIX WING MIRROR                 | \$120.00           | \$0.00                              |
| TO REPLACE SUNDRY PARTS                         | \$100.00           | \$0.00                              |
| TO CHECK WIRING AND SYSTEM FUNCTION             | \$80.00            | \$20.00                             |
| TO TRANSFER DOOR MECHANISM                      | \$120.00           | \$0.00                              |
| TO WASH AND VACUUM                              | \$60.00            | \$0.00                              |
| <b>Total Other Costs</b>                        | <b>\$720.00</b>    | <b>\$80.00</b>                      |

**Part 4 - Spare Parts / Material Usage**

| Part Number | Portion | Stock Number | Part Name                           | Quantity | List Price (\$) | Discount (%) | Final Price (\$) | Estimator Approved | Surveyor Approved |
|-------------|---------|--------------|-------------------------------------|----------|-----------------|--------------|------------------|--------------------|-------------------|
|             |         | 5310147080   | GRILLE SUB-ASSY                     | 0.00     | \$335.60        | 0.00         | \$0.00           | Replace            | Not Given         |
|             |         | 5216116010   | CLIPS PIECE, FRT & RR BUMPER        | 10.00    | \$1.50          | 25.00        | \$11.25          | Replace            | Replace           |
|             |         | 5142047030   | COVER ASSY, ENGINE                  | 0.00     | \$180.10        | 0.00         | \$0.00           | Replace            | Check             |
|             |         | 5141047020   | COVER ASSY, ENGINE UNDER CENTER SET | 0.00     | \$452.80        | 0.00         | \$0.00           | Replace            | Check             |
|             |         | 8121047020   | LAMP ASSY, FOG, RH                  | 1.00     | \$910.20        | 10.00        | \$819.18         | Replace            | Replace           |
|             |         | 8122047020   | LAMP ASSY, FOG, LH                  | 0.00     | \$910.20        | 0.00         | \$0.00           | Replace            | Not Given         |
|             |         | 8118547691   | UNIT, HEADLAMP, LH                  | 0.00     | \$2,558.90      | 0.00         | \$0.00           | Replace            | Not Given         |

X  
√  
X  
X  
√  
X  
X

# SMRT Accident Vehicle Repair Estimates

|                                            |
|--------------------------------------------|
| SMRT Automotive Services Pte Ltd           |
| 60 Woodlands Industrial Park E4, Singapore |
| FAX Number : 63685562                      |
| Estimator Telephone Number : 68662623      |
| Accident Reporting Number : 68662672       |

Date Generated : 04/05/2021  
User ID : PohSuan

|              |                                       |      |             |        |            |         |           |     |
|--------------|---------------------------------------|------|-------------|--------|------------|---------|-----------|-----|
| 8114547691   | UNIT , HEADLAMP , RH                  | 0.00 | \$2,558.90  | 0.00   | \$0.00     | Replace | Check     | X   |
| 8101647690   | COMPUTER SUB-ASSY, HEADLAMP, RH NO.1  | 0.00 | \$486.40    | 0.00   | \$0.00     | Replace | Not Given | X   |
| 8105647690   | COMPUTER SUB-ASSY, HEADLAMP, LH NO.1  | 0.00 | \$486.40    | 0.00   | \$0.00     | Replace | Not Given | X   |
| 5320547900   | SUPPORT S/A UPPER,                    | 0.00 | \$364.90    | 0.00   | \$0.00     | Replace | Not Given | X   |
| 5320247901   | SUPPORT S/A RH                        | 0.00 | \$237.00    | 0.00   | \$0.00     | Replace | Not Given | X   |
| 5320347901   | SUPPORT S/A LH                        | 0.00 | \$237.00    | 0.00   | \$0.00     | Replace | Not Given | X   |
| 5302847010   | SUPPORT SUB-ASSY LOWER                | 0.00 | \$397.40    | 0.00   | \$0.00     | Replace | Not Given | X   |
| 5380147080   | FENDER SUB-ASSY, FR , RH              | 1.00 | \$933.10    | 25.00  | \$699.83   | Replace | Replace   | ✓   |
| 7537447140   | EMBLEM, SIDE PANEL (HYBRID)           | 1.00 | \$52.90     | 25.00  | \$39.68    | Replace | Replace   | ✓   |
| 5387547070   | LINER, FR FENDER, RH                  | 1.00 | \$198.40    | 25.00  | \$148.80   | Replace | Replace   | ✓   |
| 5385147061   | PAD, FR WHEEL RH                      | 0.00 | \$57.70     | 0.00   | \$0.00     | Replace | Not Given | X   |
| 42611-47450  | WHEEL, DISC FRONT                     | 1.00 | \$1,555.10  | 25.00  | \$1,166.33 | Replace | Replace   | ✓   |
| 5330147110   | HOOD SUB-ASSY                         | 0.00 | \$938.40    | 0.00   | \$0.00     | Replace | Not Given | X   |
| 6873012120   | HINGE ASSY, FRONT DOOR , LOWER RH     | 0.00 | \$92.10     | 0.00   | \$0.00     | Replace | Not Given | X   |
| 6871012151   | HINGE ASSY, FRONT DOOR , UPPER RH     | 0.00 | \$82.10     | 0.00   | \$0.00     | Replace | Not Given | X   |
| 6861047040   | CHECK ASSY, FRONT DOOR                | 0.00 | \$153.50    | 0.00   | \$0.00     | Replace | Not Given | X   |
|              | STICKER DECAL SMRT (DOOR)             | 1.00 | \$60.00     | 0.00   | \$60.00    | Replace | Replace   | ✓mc |
| 6700147152   | PANEL SUB-ASSY, FRONT DOOR RH         | 1.00 | \$1,249.60  | 100.00 | \$0.00     | Replace | Repair    | R   |
| 8791547070A1 | COVER, OUTER MIRROR, RH               | 0.00 | \$89.50     | 0.00   | \$0.00     | Replace | Not Given | X   |
| 8791047450   | MIRROR ASSY, OUTER REAR VIEW , RH     | 0.00 | \$1,373.50  | 0.00   | \$0.00     | Replace | Not Given | X   |
| 7585047910   | MOULDING ASSY, BODY ROCKER PANEL , RH | 0.00 | \$576.00    | 0.00   | \$0.00     | Replace | Not Given | X   |
|              | TYRE                                  | 0.00 | \$126.74    | 0.00   | \$0.00     | Replace | Not Given | X   |
| 4355047020   | HUB & BEARING ASSY, RH & LH           | 0.00 | \$554.20    | 0.00   | \$0.00     | Replace | Check     | X   |
| 5311247240   | GRILLE, RADIATOR                      | 0.00 | \$165.00    | 0.00   | \$0.00     | Replace | Not Given | X   |
| 7531047060   | EMBLEM ASSY FRONT                     | 0.00 | \$87.10     | 0.00   | \$0.00     | Replace | Not Given | X   |
| 5261847090   | ABSORBER, FR BUMPER LOWER             | 0.00 | \$117.00    | 0.00   | \$0.00     | Replace | Check     | X   |
| 5213247010   | REINFORCEMENT FRONT LOWER             | 0.00 | \$238.50    | 0.00   | \$0.00     | Replace | Not Given | X   |
| 5210247020   | EXTENSION SUB-ASSY, RH                | 0.00 | \$116.30    | 0.00   | \$0.00     | Replace | Not Given | X   |
| 5210347010   | EXTENSION SUB-ASSY, LH                | 0.00 | \$116.30    | 0.00   | \$0.00     | Replace | Not Given | X   |
| 5261147140   | ABSORBER, FR BUMPER                   | 0.00 | \$70.30     | 0.00   | \$0.00     | Replace | Check     | X   |
| 5202147110   | REINFORCEMENT FRONT UPPER             | 1.00 | \$691.10    | 100.00 | \$0.00     | Replace | Repair    | R   |
| 5212747907   | COVER, FR BUMPER RH                   | 0.00 | \$28.10     | 0.00   | \$0.00     | Replace | Not Given | X   |
| 5211647050   | SUPPORT, FR BUMPER LH                 | 0.00 | \$82.30     | 0.00   | \$0.00     | Replace | Not Given | X   |
| 5211547050   | SUPPORT, FR BUMPER RH                 | 1.00 | \$76.90     | 25.00  | \$57.68    | Replace | Replace   | ✓   |
| 5211947962   | COVER, FR BUMPER                      | 1.00 | \$495.50    | 25.00  | \$371.63   | Replace | Replace   | ✓   |
| Total        |                                       |      | \$20,494.54 |        | \$3,374.38 |         |           |     |

## Added Spare Parts / Material Usage After Surveyor Signed off

| Part Number | Portion | Stock Number | Part Name                 | Quantity | List Price \$ | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check |
|-------------|---------|--------------|---------------------------|----------|---------------|--------------|------------------|-----------|----------------|
|             |         | 5202147110   | REINFORCEMENT FRONT UPPER | 0.00     | \$691.10      | 0.00         | \$0.00           | Replace   | Not Given      |
|             |         | 5261847090   | ABSORBER, FR BUMPER LOWER | 0.00     | \$117.00      | 0.00         | \$0.00           | Replace   | Not Given      |
|             |         | 5142047030   | COVER ASSY, ENGINE        | 0.00     | \$180.10      | 0.00         | \$0.00           | Replace   | Not Given      |
|             |         | 8114547691   | UNIT , HEADLAMP , RH      | 1.00     | \$2,558.90    | 10.00        | \$2,303.01       | Replace   | Replace        |



# SMRT Accident Vehicle Repair Estimates

|                                            |
|--------------------------------------------|
| SMRT Automotive Services Pte Ltd           |
| 60 Woodlands Industrial Park E4, Singapore |
| FAX Number : 63685592                      |
| Estimator Telephone Number : 68662623      |
| Accident Reporting Number : 68662672       |

Date Generated : 04/05/2021

User ID : PohSuan

|       |                |                          |      |          |      |          |         |           |                       |
|-------|----------------|--------------------------|------|----------|------|----------|---------|-----------|-----------------------|
|       | 53101470<br>80 | GRILLE SUB-ASSY          | 0.00 | \$335.60 | 0.00 | \$0.00   | Replace | Not Given | X <i>UP</i> <i>Sn</i> |
|       | 52114471<br>90 | BRACKET, FR BUMPER       | 0.00 | \$99.80  | 0.00 | \$0.00   | Replace | Not Given | X <i>UP</i> <i>Sn</i> |
|       | 17753370<br>10 | INLET, AIR CLEANER, NO 3 | 0.00 | \$35.30  | 0.00 | \$0.00   | Replace | Not Given | X <i>UP</i> <i>Sn</i> |
|       |                | NUMBER PLATE             | 0.00 | \$35.00  | 0.00 | \$0.00   | Replace | Not Given | X <i>UP</i> <i>Sn</i> |
| Total |                |                          |      | 4,052.80 |      | 2,303.01 |         |           |                       |

5,677.39 L/S \$5,550/-  
-20%  
4541.91  
+ 350  
+ 680  
5,571.91