


Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60	
Main	TO REMOVE AND REFIX WING MIRROR	120.00	0	
Main	TO REPLACE SUNDRY PARTS	100.00	0	
Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
6 Main	TO TRANSFER DOOR MECHANISM	120.00	0	
7 Main	TO WASH AND VACUUM	60.00	0	
Total:		720.00	80.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	13,456.30	2,699.49
Total Labour Cost	676.00	350.00
Total Spray Painting	2,232.00	600.00
Other	720.00	80.00
Overall Total	17,084.30	3,729.49
Lump Sum Repair Option	☐	☒
Lump Sum Total	17,100.00	3,750.00
Surveyor Approved Amount		3,750.00
No of Repair Days*	6	3
Remarks	-	Lump Sump repair, resurvey after paint. \ FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR Kenneth Kong (LKK) HP : 9691 0663 / Email :
Surveyor Name		Kenneth Kong (LKK)
Signature		
Survey Date		

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to ~~final~~ approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Save

Clear