

Section A - Accident Details

Registration Number	SHB738A
Case Reference Number	TAX/04/21/2039
Registration Date	1/4/2016
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	SEBASTIAN TUANG
Type of Accident	Side Swipe
Accident Date and Time	14/4/2021 7:26 AM
Accident Reported Date and Time	14/4/2021 9:30 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24110499
Special Instruction to ARC, if any	TP /TOWED \$40 / CHINA TAIPING - LKK
Prepared Date and Time	15/4/2021 9:12 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$300.00
Total Spray Cost	\$1,296.00	\$450.00
Total Spare Part Cost	\$8,782.70	\$1,157.78
Total Other Cost	\$636.00	\$180.00
TOTAL COST	\$11,390.70	\$2,087.78
Lump Sum Total	\$11,400.00	\$2,100.00 (L/S)
Number of Repair Days	6.0	3.0
Prepared / Adjusted By	Ang Bang Kien	Sun Pin (LKK) / China Taiping
ARC / Surveyor Sign Off Date	15/04/2021 5:19 PM	15/04/2021 4:16 PM
Signature		
Remarks		L/S, after paint photo.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2104-0437	Invoice Number	
Quotation Date	26.04.2021	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	\$676.00	\$300.00 /
Total Labour	\$676.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00 /
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$0.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00 /
TO RESPRAY RIM	\$180.00	\$50.00 /
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,296.00	\$450.00 /

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00 /
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$30.00 /
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00 /
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00 /
TO WASH AND VACUUM	\$60.00	\$0.00
TOWING CHARGE / Nec	\$56.00	\$40.00 /
Total Other Costs	\$636.00	\$180.00 /

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		81521-47050	LENS & BODY,FR TURN LH	0.00	\$511.80	0.00	\$0.00	Replace	Not Given X
		81170-47500	HEAD LAMP LH	0.00	\$945.20	0.00	\$0.00	Replace	Not Given X
		81130-47500	HEAD LAMP RH	1.00	\$945.20	10.00	\$850.68	Replace	Replace /
		53201-47902	SUPPORT SUB-ASSY	0.00	\$1,460.40	0.00	\$0.00	Replace	Not Given X
		53852-47020	FENDER LINER PAD, FR WHEEL LH	0.00	\$49.30	0.00	\$0.00	Replace	Not Given X
		53876-47030	FENDER LINER FRT/LH	0.00	\$171.70	0.00	\$0.00	Replace	Not Given X
		43410-47030	DRIVE SHAFT RH	0.00	\$1,764.40	0.00	\$0.00	Replace	Not Given X
		45046-49225	TIE ROD END RH	0.00	\$159.30	0.00	\$0.00	Replace	Not Given X
		48068-47050	LOWER ARM FRT/RH	0.00	\$625.90	0.00	\$0.00	Replace	Check X
		43550-47011	WHEEL HUB FRT	0.00	\$549.70	0.00	\$0.00	Replace	Check X
			TYRE	1.00	\$126.74	0.00	\$126.74	Replace	Replace /
		42611-47140	WHEEL DISC. FRONT	1.00	\$1,484.20	100.00	\$0.00	Replace	Repair /

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number : 6365592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 26/04/2021

User ID : PohSuan

53851-47040	FENDER LINER PAD, FR WHEEL RH	0.00	\$49.30	0.00	\$0.00	Replace	Not Given	X
53875-47030	FENDER LINER FRT/RH	0.00	\$171.70	0.00	\$0.00	Replace	Check	X
75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	
53801-47050	FENDER FRT/RH	1.00	\$723.40	100.00	\$0.00	Replace	Repair	X
16533-28051	SUPPORT RADIATOR, RH	0.00	\$54.50	0.00	\$0.00	Replace	Not Given	X
51410-12105	UNDER COVER CENTER	0.00	\$448.30	0.00	\$0.00	Replace	Not Given	X
52618-47050	BUMPER FRT ABSORBER LOWER	0.00	\$127.70	0.00	\$0.00	Replace	Not Given	X
76851-47020	BUMPER LIP FRT	0.00	\$139.60	0.00	\$0.00	Replace	Not Given	X
53113-47040	GRILLE, RADIATOR LOWER NO.2	0.00	\$94.60	0.00	\$0.00	Replace	Not Given	X
53111-47040	GRILLE, RADIATOR	0.00	\$310.60	0.00	\$0.00	Replace	Not Given	X
53289-47032	COVER, RADIATOR	0.00	\$122.80	0.00	\$0.00	Replace	Not Given	X
81511-47050	LENS & BODY, FR TURN RH	0.00	\$511.80	0.00	\$0.00	Replace	Check	X
81210-12230	FOG LAMP RH	0.00	\$295.20	0.00	\$0.00	Replace	Not Given	X
53102-47020	BUMPER GRILLE SUB-ASSY, LOWER	0.00	\$311.10	0.00	\$0.00	Replace	Not Given	X
52127-47903	COVER, FR BUMPER HOLE RH	0.00	\$18.50	0.00	\$0.00	Replace	Not Given	X
57013-47030	ARM SUB-ASSY, FR BUMPER RH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given	X
57014-47030	ARM SUB-ASSY, FR BUMPER LH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given	X
52021-47023	BUMPER REINFORCEMENT FRT	0.00	\$498.40	0.00	\$0.00	Replace	Not Given	X
52611-47080	BUMPER ENERGY ABSORBER FRT	0.00	\$78.80	0.00	\$0.00	Replace	Not Given	X
52116-47040	BUMPER SUPPORT F/LH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given	X
52115-47040	BUMPER SUPPORT F/RH	1.00	\$76.40	25.00	\$57.30	Replace	Replace	
52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace	
52119-47930	BUMPER FRT	1.00	\$482.00	25.00	\$361.50	Replace	Replace	
Total			\$13,939.25		\$1,447.23			

SVC

SVC

NEC

R

SVC

SVC

SVC

SVC

SVC

SVC

SVC

SVC

SVC

SVC

SVC

SVC

SVC

SVC

SVC

BR

NEC

Def

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

1447.23 /
- 202
1157.78 /
+ 300.00 /
+ 630.00 /
2087.78 /
L/s \$2100 /
3 days
SHB 738A



Factory Japan 2020.0.1 : Toyota : Prius : W30 Series : ZVW30 (Modified Specification)
4-Wheel Total Alignment

Front : Left

Actual	Before	Specified Range
-0°41'	-0°43'	-0°55' 0°35'
5°59'	5°59'	5°00' 6°30'
0°00'	0°06'	-0°04' 0°07'
12°47'	12°49'	11°20' 12°50'
12°08'	12°06'	10°25' 13°25'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°43'		-0°55' 0°35'
5°27'		5°00' 6°30'
0°21'	0°22'	-0°04' 0°07'
12°12'		11°20' 12°50'
12°15'		10°25' 13°25'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-0°27'	-0°29'	
0°32'	0°32'	
0°29'	0°31'	
0°01'	0°28'	-0°09' 0°14'

Rear : Left

Actual	Before	Specified Range
-1°18'	-1°20'	-2°00' -1°00'
0°09'	0°09'	-0°03' 0°14'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°10'		-2°00' -1°00'
0°12'		-0°03' 0°14'

Rear

Cross Camber
Total Toe
Thrust Angle
Axle Offset

Actual	Before	Specified Range
0°08'	0°03'	
0°21'	0°20'	-0°06' 0°28'
-0°01'	-0°01'	
0mm	0mm	