

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21004893/UBS3Q2
Date: 18/06/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SMF8758J	Insured Vehicle No :	SLQ7687R
Date of Loss:	16/04/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0001646

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF8758J		
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Engine No:	L15B5552995
Reg. Date:	28/11/2018 (Man. Year: 2018)	Chassis No:	RU11302988
Colour:	Black	Odometer:	35430 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	KAPSEN 6 mm	Rear Left Side:	KAPSEN 6 mm
Front Right Side:	KAPSEN 6 mm	Rear Right Side:	KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,298.00	1,553.04	2,744.96	63.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,670.00	1,460.00	1,210.00	45.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,968.00	3,013.04	3,954.96	56.76
Approved Total (Overridden) (S\$)		2,400.00		

Nett Amount (S\$)	6,968.00	2,400.00	4,568.00	65.56
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,707.45		
Global Sum Settlement (S\$)		2,600.00		

INSPECTION

Date of Assignment: 19/04/2021

Date Inspected: 20/04/2021

Estimated Period of Repair: 4.0 days

Inspected At:

CHOO MOTOR SPRAY PAINTER
 1 KAKI BUKIT AVENUE 6
 #01-39 AUTOBAY@KAKI BUKIT
 SINGAPORE 417883

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 May 2021)
Parts:	M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMF8758J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	762.20 F	*588.20 FL
2	1		*REAR BUMPER REFLECTOR O/S	Not Necessary	151.00 F	*- FL
3	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
4	1		*REAR BUMPER SIDE O/S	Distorted	295.20 F	*192.20 FL
5	1		*REAR FENDER O/S	Repair	987.60 F	*- FL
6	1		*REAR FENDER OUTER PROTECTOR O/S	Torn	285.50 F	*199.50 FL
7	1		*REAR FENDER INNER LOWER PANEL O/S	Dented	425.20 F	*425.20 FL
8	1		*REAR END PANEL	Repair	575.10 F	*- FL
9	1		*TAILLAMP O/S	Cracked	486.20 F	*486.20 FL
10	1		*SET REAR BUMPER REVERSE SENSOR	Serviceable	280.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	4,298.00	1,941.30
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	388.26
Total Parts (\$)	4,298.00	1,553.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REFIX REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
4	TO SPRAY RUST PROOFING	New	60.00	30.00
5	TO CONDUCT WHEEL ALIGNMENT	New	80.00	0.00
6	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,080.00	700.00
7	TO PUTTY & SPRAY PAINTING	New	1,200.00	580.00
Gross Labour Cost (S\$)			2,670.00	1,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >