

Lee HSIAToy

Not Authorized
Lee

19/4/21

2/5 @ 2600/
3 days.

FASTECH AUTO PTE LTD
BLK 1 KAKI BUKIT AVE 6
#01-48 AUTOBAY
SINGAPORE 417883

VEHICLE No: SJC 7746B

NETT ITEM

1PC	FRONT BUMPER SPORT TYPE	de/Win	950	\$1,500.00 ✓
1PC	FRONT BUMPER REINFORCEMENT	n		\$212.00 X
1PC	FRONT BUMPER LICENCE PLATE GARNISH	De	65	\$85.00 ✓
1PC	FRONT GRILLE	one		\$231.00 ✓
				\$2,028.00
			LESS10%	\$1,825.20

S.NETT ITEM

1PC	FRONT BUMPER LOWER SPOILER	one		\$1,800.00 1100
1SET	FRONT BUMPER CLIPS	her		\$50.00 40
1PC	FRONT INTER COOLER	1 n		\$1,800.00 X
1PC	FRONT BUMPER LICENCE PLATE	Daged		\$50.00 40
1SET	FRONT BUMPER SENSOR	Daged		\$180.00 ✓
	TO CHECK WIRING			\$50.00 20
	TO DISMANTLE & REPLACED FRT BUMPER SENSOR			\$80.00 50
	TO REFILL AIR CON GAS			1 n \$120.00 X
	LABOUR FOR PANEL BEATING & REPLACED PARTS			\$680.00 300
	TO PUTTY & SPRAY PAINTING			\$800.00 400
			TOTAL	\$7,435.20

1-1246

102

1-1124.4

S.N-1360

2-770.

3257.4

202

2621

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: