

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No: SLS4246P
Chassis No:
Engine No:

Report No :
Date : 19.04.2021

Replacement of Damaged Parts

S/No.	Quantity	Description	Condition / Remarks	Repairer's Estimates	My Recommendation
1	1	Front Right Door	Damaged	\$ 1,556.00	\$ 1,400.40 X R
2	1	Front Right Door Hinge	Necessary	\$ 145.00	\$ 130.50 X / CUT
3	1	Front Right Door Garnish	Scratched	\$ 169.00	\$ 152.10 / OD
4	1	Rear Right Door	Damaged	\$ 1,986.00	\$ 1,787.40 X
5	1	Front Rear Door Hinge	Necessary	\$ 145.00	\$ 130.50 X / CUT
6	1	Right Rear Door Garnish	Damaged	\$ 184.00	\$ 165.60 / CUT
7	1	Right Rear Fender Garnish	Damaged	\$ 109.00	\$ 98.10 / CUT
8	1	Rear Bumper	Damaged	\$ 1,579.00	\$ 1,421.10 X
9	1	Rear Bumper Bracket Right	Necessary	\$ 54.00	\$ 48.60 X
10	1	Rear Right Alloy Sport Rims	Damaged	\$ 1,850.00	\$ 1,665.00 / CUT
12	1	Right Rear Fender	Damaged	\$ 1,745.00	\$ 1,570.50 / CUT
				\$ 9,522.00	\$ 7,617.60 X R

Total (Parts): \$ 9,522.00 -20% \$ 7,617.60

Labour Charges

26	To fix & dismantle and remove damaged Frontal right to rear; affected damaged portion.	\$ 1,200.00	400
27	To apply anti rust coat and affected areas	\$ -	X
28	To check wiring	\$ 180.00	30
29	Welding and cutting of affected panels, including chassis alignment.	\$ 800.00	X
30	Spray painting for Frontal right to Rear Portions affected parts	\$ 1,800.00	700
31	Refocusing of the front headlamp	\$ -	
32	Diagnose ECU system and reset error code.	\$ 120.00	X
33	3D Wheel Alignment	\$ 180.00	60
34	To Apply Waterproofing sealer on End Panels	\$ -	X
		Total Labour: \$ 4,280.00	

Total cost of repairs (Total cost of parts + Total Labour Cost) \$ 11,897.60

Less 20% \$ 9,518.08

AMM PTE LTD

Page 2 of 3

Steve CLKK) WL AL

8327 8813

*4 yrs
L/S*

Ry AL Sy

19/4/21

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: