

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No: SLS4246P

Chassis No:

Engine No:

Report No :

Date

: 19.04.2021

Replacement of Damaged Parts

S/No.	Quantity	Description	Condition / Remarks	Repairer's Estimates	My Recommendation
1	1	Front Right Door	Damaged	\$ 1,556.00	\$ 1,400.40
2	1	Front Right Door Hinge	Necessary	\$ 145.00	\$ 130.50
3	1	Front Right Door Garnish	Scratched	\$ 169.00	\$ 152.10
4	1	Rear Right Door	Damaged	\$ 1,986.00	\$ 1,787.40
5	1	Front Rear Door Hinge	Necessary	\$ 145.00	\$ 130.50
6	1	Right Rear Door Garnish	Damaged	\$ 184.00	\$ 165.60
7	1	Right Rear Fender Garnish	Damaged	\$ 109.00	\$ 98.10
8	1	Rear Bumper	Damaged	\$ 1,579.00	\$ 1,421.10
9	1	Rear Bumper Bracket Right	Necessary	\$ 54.00	\$ 48.60
10	1	Rear Right Alloy Sport Rims	Damaged	\$ 1,850.00	\$ 1,665.00
12	1	Right Rear Fender	Damaged	\$ 1,745.00	\$ 1,570.50
				\$ 9,522.00	\$ 7,617.60

Total (Parts): \$ 9,522.00 -20% \$ 7,617.60

Labour Charges

26	To fix & dismantle and remove damaged Frontal right to rear; affected damaged portion.	\$ 1,200.00
27	To apply anti rust coat and affected areas	\$ -
28	To check wiring	\$ 180.00
29	Welding and cutting of affected panels, including chassis alignment.	\$ 800.00
30	Spray painting for Frontal right to Rear Portions affected parts	\$ 1,800.00
31	Refocusing of the front headlamp	\$ -
32	Diagnose ECU system and reset error code.	\$ 120.00
33	3D Wheel Alignment	\$ 180.00
34	To Apply Waterproofing sealer on End Panels	\$ -
Total Labour:		\$ 4,280.00

Total cost of repairs (Total cost of parts + Total Labour Cost) \$ 11,897.60

Less 20% \$ 9,518.08

AMM PTE LTD

Page 2 of 3

Steve CLKK) W/L AL

8322 8813

4 dys

L/S

Ry AL Sy

19/4/21

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: