

TO :

ESTIMATE REPORT

1ST Quotation

FAX NO:

19/04/2021 11:00

JOB-NO: 50113302

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHC0578P

TRANS: AUTO

CHASSIS: JTDKB3FU303079810

MAKE / MODEL: TOYOTA / Prius Hybrid 1.8 CVT

ENGINE: 2ZR2C06352

OWNER'S INSURER: AXA INSURANCE SINGAPORE PTE LTD

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 STRAIGHTEN AND PANEL BEAT OF ACCIDENT AREA	1.00	1,100.00	0.00	1,100.00	Y		400 ✓
2 TO RUST PROOFING OF THE AFFECTED AREA	1.00	180.00	0.00	180.00	Y		40 ✓
3 TO REMOVE AND REFIT NECESSARY ITEMS TO FACILITATE REPAIR	1.00	250.00	0.00	250.00	Y		X 17 ✓
4 TO DIAGNOSTIC, CHECK WIRING AND LIGHTING SYSTEM AND CLEAR FAULT CODE	1.00	270.00	0.00	270.00	Y		100 ✓
5 TO TRANSFER FRONT BUMPER MECHANISM TO NEW BUMPER AND CONDUCT WATER SEEPAGE TEST	1.00	170.00	0.00	170.00	Y		X 17 ✓
6 TO READJUST AND REALIGN HEADLAMP AIM	1.00	150.00	0.00	150.00	Y		X 17 ✓
7 TO REMOVE AND REFIT FRONT UNDERCARRIAGE TO ENABLE REPAIR	1.00	250.00	0.00	250.00	Y		100? X 17 ✓
8 TO CONDUCT TYRE BALANCING AND WHEEL ALIGNMENT	1.00	130.00	0.00	130.00	Y		30 ✓
9 TO RESPRAY FRONT BUMPER	1.00	250.00	0.00	250.00	Y		200 ✓
10 TO RESPRAY FRONT BONNET	1.00	250.00	0.00	250.00	Y		X 17 ✓
11 TO RESPRAY FRONT LH FENDER PANEL	1.00	250.00	0.00	250.00	Y		200 ✓
12 TO RESPRAY FRONT LH SIDE MIRROR	1.00	250.00	0.00	250.00	Y		100 ✓
TOTAL:		3,500.00	0.00	3,500.00			

MATERIALS

1 FRONT BUMPER <i>tan</i>	1.00	490.60	122.65	367.95 ✓	L	Y	
2 FRONT LH BUMPER RETAINER <i>cm</i>	1.00	96.20	24.05	72.15 ✓	L	Y	
3 FRONT LH HEADLAMP <i>cm</i>	1.00	2,760.51	690.13	2,070.38 ✓	L	Y	
4 FRONT LH FOG LAMP <i>? xsu</i>	1.00	970.50	242.63	727.87	L	Y	
5 RADIATOR GRILLE <i>Xnn</i>	1.00	398.20	99.55	298.65	L	Y	
6 ENGINE UNDER COVER NO.2 <i>Xnn</i>	1.00	287.60	71.90	215.70	L	Y	
7 RADIATOR GRILLE LOWER NO.1 <i>Xnn</i>	1.00	198.60	49.65	148.95	L	Y	
8 FRONT BUMPER LOWER ABSORBER <i>Xnn</i>	1.00	148.59	37.15	111.44	L	Y	
9 FRONT BUMPER ENERGY ABSORBER <i>Xnn</i>	1.00	138.86	34.72	104.14	L	Y	
10 HEADLAMP COMPUTER <i>Xnn</i>	1.00	786.30	196.58	589.72	L	Y	
11 HEADLAMP LEVELLING MOTOR LH <i>Xnn</i>	1.00	633.21	158.30	474.91	L	Y	
12 RADIATOR GRILLE EMBLEM <i>Xnn</i>	1.00	139.65	34.91	104.74	L	Y	
13 FRONT LH FENDER PANEL <i>de</i>	1.00	988.70	247.18	741.52 ✓	L	Y	
14 FRONT LH FENDER LINER <i>de</i>	1.00	213.30	53.33	159.97 ✓	L	Y	
15 FRONT LH FENDER EMBLEM <i>nn</i>	1.00	75.86	18.97	56.89 ✓	L	Y	

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
16 FRONT LH WHEEL RIM <i>Report</i>	1.00	1,655.50	413.88	1,241.62	L	Y	
17 FRONT LH TYRE 195/65/15 <i>Xnn</i>	1.00	265.57	66.39	199.18	L	Y	
18 FRONT LH WHEEL CAP <i>Xnn</i>	1.00	285.90	71.48	214.42	L	Y	
19 FRONT LH KNUCKLE ARM <i>?xsu</i>	1.00	496.50	124.13	372.37	L	Y	
20 FRONT LH KNUCKLE HUB+BEARING <i>?xsu</i>	1.00	388.40	97.10	291.30	L	Y	
21 FRONT LH LOWER ARM <i>?xsu</i>	1.00	420.98	105.25	315.73	L	Y	
22 FRONT LH SHOCK ABSORBER ASSY <i>xsu</i>	1.00	461.10	115.28	345.82	L	Y	
23 FRONT LH STABILIZER LINK <i>xsv</i>	1.00	135.96	33.99	101.97	L	Y	
24 FRONT LH DRIVE SHAFT <i>xsv</i>	1.00	1,389.55	347.39	1,042.16	L	Y	
25 FRONT BUMPER REINFORCEMENT <i>xsv</i>	1.00	751.90	187.98	563.92	L	Y	
26 HEADLAMP BRACKET LH <i>?xsu</i>	1.00	186.90	46.73	140.17	L	Y	
27 FRONT LH BUMPER SIDE BRACKET <i>xsu</i>	1.00	198.55	49.64	148.91	L	Y	
28 FRONT BUMPER CLIP SET <i>na</i>	1.00	85.00	0.00	85.00	S	Y	
29 FRONT FENDER LINER CLIP SET <i>na</i>	1.00	75.00	0.00	75.00	S	Y	
30 RADIATOR GRILLE CLIP SET <i>xnn</i>	1.00	70.00	0.00	70.00	S	Y	
31 FRONT BUMPER RETAINER CLIP <i>xnn</i>	1.00	60.00	0.00	60.00	S	Y	
32 ENGINE UNDER COVER CLIP <i>xnn</i>	1.00	65.00	0.00	65.00	S	Y	
33 RADIATOR GRILLE TOP GARNISH CLIP <i>xnn</i>	1.00	65.00	0.00	65.00	S	Y	
34 FRONT VEHICLE NUMBER PLATE WITH FRAME <i>xnn</i>	1.00	150.00	0.00	150.00	S	Y	
TOTAL:		15,533.49	740.94	11,792.55			
TOTAL PARTS & LABOUR :		19,033.49	3,740.94	15,292.55			

EXCESS/LOADING:SS 0.00

No. Of Day:

RE-SURVEY: BEFORE AFTER PAINTING

PART-BY-PART OF LUMP SUM:SS

DATE OF SURVEY: 20 / 04 / 21 @ 1440

SURVEYED BY:

CONTACT NO:

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: