

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0117/2021
DATE : 16-APR-2021

INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04-05 IOB BUILDING
S(049711)
TEL : 63476100
FAX : 62244174
ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : MISS CHOO AI LING FELICIA
ADDRESS : BLK 106 BUKIT PURMEI ROAD
#05-130
S(090106)
TELEPHONE NO : 92967545/96733501

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-SLN4524M
VEHICLE NO : SMV3940Y
MODEL CODE : TDWARDZE12EDAY520Z
MODEL/YEAR : NISSAN NOTE 1.2 (V) MY 2018
ENGINE NO : HR12187394K
CHASSIS NO : JN1TAAE12Z0985144
MILEAGE : 1 KM
DATE IN : 16/04/2021
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 15/04/2021

16/04/2021

DIRECT SETTLEMENT
OWNER CLAIMING LOSS OF USE / RENTAL
CAR AT WORKSHOP / CAR NOT AT WORKSHOP
KINDLY REVERT TO ME ASAP
EMAIL : lawrenceteo@tanchong.com
H/P : 94568832 FAX : 64697472

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMV3940Y

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RITCAM	REMOVE/INSTALL & TEST REAR REVERSE CAMERA	120.00	
2	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 03	360.00	
3	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	
4	ZZ/001	REPAIR LH REAR FENDER, TAILGATE, END PANEL AND RENEW REAR BUMPER	1600.00	
5	ZZ/002	S/PAINT LH REAR FENDER, REAR BUMPER, TAILGATE AND END PANEL	1600.00	
6	ZZ/003	R/I OR RENEW REVERSE SENSOR	55.00	
7	ZZ/004	CHECK LIGHTING	48.00	
		TOTAL LABOUR CHARGES	3883.00	

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMV3940Y

		DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1	GROMET BUMPER \$3.40 EA X 02	76881-3VA0A			6.80
2	GROMMET BUMPER \$2.70 EA X 02	63846-5V000	5.40		
3	ENERGY ABSORBER	85090-5WJ0A	125.30		
4	STAY-RR BUMPER LH/RH \$96.90 EA X 02	H5212-1HMMA	193.80		
5	BRKT BUMPER LH	85221-3VA0C	50.20		
6	CLIP BUMPER \$1.30 EA X 03	01553-10501	3.90		
7	FACE-RR BUMPER	85022-5WJ0H	460.00		
8	CLIP BUMPER \$1.30 EA X 10	01553-09611	13.00		
9	EMBLEM	90892-3VA0A	79.90		
10	EMBLEM-BACK DOO	90890-3VA0A	64.90		
11	CLIP CLOSING \$1.40 EA X 06	01553-09321	8.40		
12	CLOSING PLATE-RR LH	78819-5WJ0A	48.80		
13	CLIP C/LAMP	73998-3VA0A			2.80
14	GROMET C/LAMP	26557-2U001	4.90		
15	GROMET C/LAMP	26557-2U000	4.90		
16	LAMP COMB RR,LH	26555-5WK0A	435.80		
17	SUNDRIES	NPN			100.00
18	SENSOR-REVERSE	SENSOR			250.00
SUB TOTAL			1499.20	0.00	359.60
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			299.84	0.00	0.00
GRAND TOTAL			1199.36	0.00	359.60
OVERALL TOTAL			1558.96		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMV3940Y

TOTAL LABOUR CHARGES 3883.00
TOTAL SPARE PARTS CHARGES 1558.96

GRAND TOTAL 5441.96 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

PLS NOTE : This estimate is based on visual inspection of the
 affected vehicle. Should we require further labour
 charges & spare parts in the process of repairs, we
 shall inform you accordingly.