

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0117/2021
DATE : 16-APR-2021

INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04-05 IOB BUILDING
S(049711)
TEL : 63476100
FAX : 62244174
ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : MISS CHOO AI LING FELICIA
ADDRESS : BLK 106 BUKIT PURMEI ROAD
#05-130
S(090106)
TELEPHONE NO : 92967545/96733501

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-SLN4524M
VEHICLE NO : SMV3940Y
MODEL CODE : TDWARDZE12EDAY520Z
MODEL/YEAR : NISSAN NOTE 1.2 (V) MY 2018
ENGINE NO : HR12187394K
CHASSIS NO : JN1TAAE12Z0985144
MILEAGE : 1 KM
DATE IN : 16/04/2021
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 15/04/2021

16/04/2021
163ce

DIRECT SETTLEMENT
OWNER CLAIMING LOSS OF USE / RENTAL
CAR AT WORKSHOP / CAR NOT AT WORKSHOP
KINDLY REVERT TO ME ASAP
EMAIL : lawrenceteo@tanchong.com
H/P : 94568832 FAX : 64697472

~~LXX~~
APPT
3pm

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMV3940Y

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RITCAM	REMOVE/INSTALL & TEST REAR REVERSE CAMERA	120.00	/
2	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 03	360.00	240
3	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	X
4	ZZ/001	REPAIR LH REAR FENDER, TAILGATE, END PANEL AND RENEW REAR BUMPER	1600.00	780
5	ZZ/002	S/PAINT LH REAR FENDER, REAR BUMPER, TAILGATE AND END PANEL	1600.00	750
6	ZZ/003	R/I OR RENEW REVERSE SENSOR	55.00	/
7	ZZ/004	CHECK LIGHTING	48.00	/
TOTAL LABOUR CHARGES			3883.00	

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMV3940Y

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
1 GROMET BUMPER \$3.40 EA X 02 <i>ne /</i>	76881-3VA0A			6.80
2 GROMMET BUMPER \$2.70 EA X 02 <i>ne /</i>	63846-5V000	5.40		
3 ENERGY ABSORBER <i>?</i>	85090-5WJ0A	125.30		
4 STAY-RR BUMPER LH/RH \$96.90 EA X 02 <i>?</i>	H5212-1HMA	193.80		
5 BRKT BUMPER LH <i>? ne /</i>	85221-3VA0C	50.20		
6 CLIP BUMPER \$1.30 EA X 03 <i>ne /</i>	01553-10501	3.90		
7 FACE-RR BUMPER <i>de /</i>	85022-5WJ0H	460.00		
8 CLIP BUMPER \$1.30 EA X 10 <i>ne /</i>	01553-09611	13.00		
9 EMBLEM <i>ne /</i>	90892-3VA0A	79.90		
10 EMBLEM-BACK DOO <i>ne /</i>	90890-3VA0A	64.90		
11 CLIP CLOSING \$1.40 EA X 06 <i>ne /</i>	01553-09321	8.40		
12 CLOSING PLATE-RR LH <i>?</i>	78819-5WJ0A	48.80		
13 CLIP C/LAMP <i>ne /</i>	73998-3VA0A			2.80
14 GROMET C/LAMP <i>ne /</i>	26557-2U001	4.90		
15 GROMET C/LAMP <i>ne /</i>	26557-2U000	4.90		
16 LAMP COMB RR, LH <i>soe /</i>	26555-5WK0A	435.80		
17 SUNDRIES <i>ne /</i>	NPN		20	100.00
18 SENSOR-REVERSE <i>?</i>	SENSOR			250.00
SUB TOTAL		1499.20	0.00	359.60
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		299.84	0.00	0.00
GRAND TOTAL		1199.36	0.00	359.60
OVERALL TOTAL		1558.96		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMV3940Y

TOTAL LABOUR CHARGES	3883.00
TOTAL SPARE PARTS CHARGES	1558.96
GRAND TOTAL	5441.96 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	: Rasul - Hp 90010068
SURVEYED DATE	: 19/04/21 @ 1500 hrs
AUTHORIZED DATE	: 4 days
EXCESS CLAUSE	: 0.00
LIABILITY	: 0.00
REMARKS	:

Resurvey before paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: