

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

INDIA

Owner : Sallehudin Bin Abdul Wahab

Accident Date : 10-Apr-21

Vehicle No : FBJ1274T

Vehicle Model : Honda CB400X
M

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
1	Front fender	17 \$ 196.00 X
2	Fork inner tubes	22 \$ 1,020.00 ✓
2	Fork outer tubes	17 \$ 1,040.00 X
1	Fork under bracket	17 \$ 385.00 X
1	Fork upper bracket	17 \$ 285.00 X
2	Front brake discs	17 \$ 1,120.00 X
1	Front rim shaft	17 \$ 68.00 X
1	Front sport rim	427 \$ 1,100.00 ✓
1	Handle-bar	322 \$ 175.00 ✓
1	Handle-bar end (1 set)	82 \$ 80.00 ✓
1	Hand-grip (1 set)	82 \$ 80.00 ✓
2	Side mirrors	320 \$ 190.00 ✓
1	Windscreen	320 \$ 280.00 ✓
1	Front side cover	517 \$ 550.00 ✓
1	Brake lever	72 \$ 72.00 ✓
2	Front footrests	015 320 \$ 150.00 1pc
2	Front footrest bracket	015 322 \$ 490.00 1pc
1	Brake pedal	321 \$ 180.00 ✓
1	Rear footrest	322 \$ 95.00 X
1	Radiator side cover	17 \$ 98.00 X
1	Side boards (1 set)	17 \$ 280.00 X
1	Exhaust pipe	322 \$ 1,800.00 ✓
1	Exhaust pipe protector	517 \$ 165.00 ✓
1	Master pump	72 \$ 480.00 ✓
		\$ 10,379.00
	Less 10%	\$ 1,037.90
		\$ 9,341.10

EROFIA MOTOR TRADING PTE LTD (201202259N)

No-1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Owner : Sallehudin Bin Abdul Wahab

Accident Date : 10-Apr-21

Vehicle No : FB1274T

Vehicle Model : Honda CB400X
M

Estimated Repair Costs

Special Net Items				
1	Number plate (1 set) <i>RP</i>	<i>m.s</i>	\$	28.00 <i>10</i>
2	Fork oils	<i>11</i>	\$	30.00 <i>X</i>
2	Fork oil seals	<i>11</i>	\$	56.00 <i>X</i>
1	Steering cone (1 set)	<i>11</i>	\$	150.00 <i>X</i>
1	Rear box	<i>cut</i>	\$	580.00 <i>400</i>
1	Rear box bracket	<i>11</i>	\$	180.00 <i>X</i>
1	Engine crash bar (1 set)	<i>cut</i>	\$	480.00 <i>400</i>
			\$	1,504.00

S/No.	Labour			
1	To provide towing service (LOD)	\$	50.00	<i>✓</i>
2	To check wiring and reset headlamp focusing	\$	<i>11</i> 80.00	<i>X</i>
3	To respray painting	\$	500.00	<i>300</i>
4	To repair body frame	\$	<i>11</i> 500.00	<i>X</i>
5	To provide labour	\$	600.00	<i>300</i>
			\$	1,730.00

Grand Total

\$ 12,575.10

Singapore Dollars: Twelve Thousand Five Hundred Seventy-Five and Cents: Ten only


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: