

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

INDIA Mlle cecilio

Owner : Sallehhudin Bin Abdul Wahab

Accident Date : 10-Apr-21

Vehicle No : FBJ1274T

Vehicle Model : Honda CB400X
M

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
1	Front fender	17 \$ 196.00 X
2	Fork inner tubes	22 \$ 1,020.00 X
2	Fork outer tubes	17 \$ 1,040.00 X
1	Fork under bracket	17 \$ 385.00 X
1	Fork upper bracket	17 \$ 285.00 X
2	Front brake discs	17 \$ 1,120.00 X
1	Front rim shaft	17 \$ 68.00 X
1	Front sport rim	CUT \$ 980 1,100.00 ✓
1	Handle-bar	32 \$ 175.00 ✓
1	Handle-bar end (1 set)	Page \$ 40 80.00 ✓
1	Hand-grip (1 set)	17 \$ 48 80.00 ✓
2	Side mirrors	32 \$ 190.00 ✓
1	Windscreen	32 \$ 280.00 ✓
1	Front side cover	CUT \$ 425 550.00 ✓
1	Brake lever	CM \$ 60 72.00 ✓
2	Front footrests	015 320 \$ 70 150.00 1PC
2	Front footrest bracket	015 24 \$ 215 490.00 1PC
1	Brake pedal	32 \$ 180.00 ✓
1	Rear footrest	32 \$ 95.00 X
1	Radiator side cover	17 \$ 98.00 X
1	Side boards (1 set)	17 \$ 280.00 X
1	Exhaust pipe	00 \$ 1300 1,800.00 ✓
1	Exhaust pipe protector	CUT \$ 165.00 ✓
1	Master pump	CM \$ 420 480.00 ✓
		\$ 10,379.00
	Less 10%	\$ 1,037.90
		\$ 9,341.10

*not done
22
19/4/21
2/5 \$ 4400
4 Lgs.
24/4/21*

4528

EROFIA MOTOR TRADING PTE LTD (201202259N)

No-1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Owner : Sallehhudin Bin Abdul Wahab

Accident Date : 10-Apr-21

Vehicle No : FBJ1274T

Vehicle Model : Honda CB400X
M

Estimated Repair Costs

Special Net Items

1	Number plate (1 set) <i>RP</i>	<i>m.s</i>	\$	28.00	<i>10</i>
2	Fork oils	<i>17</i>	\$	30.00	<i>X</i>
2	Fork oil seals	<i>17</i>	\$	56.00	<i>X</i>
1	Steering cone (1 set)	<i>17</i>	\$	150.00	<i>X</i>
1	Rear box	<i>cut</i>	\$	580.00	<i>400</i>
1	Rear box bracket	<i>17</i>	\$	180.00	<i>X</i>
1	Engine crash bar (1 set)	<i>cut</i>	\$	480.00	<i>400</i>
				\$	1,504.00

S/No. Labour

1	To provide towing service (LOD)	\$	50.00	✓
2	To check wiring and reset headlamp focusing	\$	17 80.00	X
3	To respray painting	\$	500.00	300
4	To repair body frame	\$	17 500.00	X
5	To provide labour	\$	600.00	300
		\$	1,730.00	

Grand Total

\$ 12,575.10

Singapore Dollars: Twelve Thousand Five Hundred Seventy-Five and Cents: Ten only

5553.2
4442


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: