



Rico 60 Auto Services Pte Ltd
Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875
Email: claims@rico60.com
Tel: 6286 6060 Fax : 6286 7060

RICO Office Use Only

Parts -%	
SN	
Labour	
Total	
Lump Sum	
ERV	

TO: AXA

Vehicle No : SKZ 6900 X

Make & Model : MAZDA 3

DATE: 17/4/2021

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE
1	FRONT DOOR LH X R	1	\$ 1,200.00	\$ 1,200.00
2	FRONT DOOR FRAME TOP RUBBER LH X	1	\$ 154.00	\$ 154.00
3	FRONT DOOR OUTER MOULDING LH ? X	1	\$ 199.60	\$ 199.60
4	FRONT DOOR INNER LOCK LH ? X	1	\$ 457.80	\$ 457.80
5	FRONT DOOR WEATHERSTRIP LH / TN	1	\$ 289.50	\$ 289.50
6	CENTER PILLER INNER TRIM LH X	1	\$ 541.00	\$ 541.00
7	ROCKER PANEL X R	1	\$ 1,245.00	\$ 1,245.00
8	REAR DOOR LH / DD	1	\$ 1,260.00	\$ 1,260.00
9	REAR DOOR FRAME TOP RUBBER LH ? X	1	\$ 89.00	\$ 89.00
10	REAR DOOR INNER STEP GARNISH LH X	1	\$ 124.00	\$ 124.00
11	REAR DOOR OUTER MOULDING LH ? / OR	1	\$ 198.00	\$ 198.00
12	REAR DOOR HINGE LH ? X	2	\$ 144.90	\$ 289.80
13	REAR DOOR CHECKER LH X	1	\$ 127.90	\$ 127.90
14	REAR DOOR OUTER HANDLE LH X	1	\$ 154.00	\$ 154.00
15	REAR DOOR OUTER HANDLE SIDE COVER LH X	1	\$ 67.60	\$ 67.60
16	REAR DOOR INNER LOCK LH ? / Jemher	1	\$ 466.90	\$ 466.90
17	REAR DOOR LOCK CATCH LH ? X	1	\$ 56.00	\$ 56.00
18	REAR DOOR WEATHERSTRIP LH / TN	1	\$ 198.00	\$ 198.00
19	REAR DOOR CHANNEL LH X	1	\$ 96.00	\$ 96.00
20	REAR DOOR CHANNEL SEAL LH X	1	\$ 178.20	\$ 178.20
21	REAR DOOR REGULATOR MOTOR LH X	1	\$ 569.20	\$ 569.20
22	REAR DOOR REGULATOR GEAR LH ? / BT	1	\$ 316.00	\$ 316.00
23	REAR DOOR INNER TRIM LH ? / OR	1	\$ 758.10	\$ 758.10
24	REAR FENDER LH / DD	1	\$ 1,241.00	\$ 1,241.00
25	REAR FENDER INNER SHIELD LH / TN	1	\$ 219.00	\$ 219.00
26	REAR FENDER QUARTER GLASS OUTER MLD X	1	\$ 158.00	\$ 158.00

27	REAR WINDSCREEN MOULDING ✓ <i>MC</i>	1	\$	295.30	\$	295.30
28	REAR WINDSCREEN INNER SEAL X <i>APK Replaced</i>	1	\$	60.00	\$	60.00
29	REAR SPORT RIM LH ✓ <i>INT</i>	1	\$	1,121.00	\$	1,121.00
30	REAR ABSORBER LH ✓ <i>MC</i> - <i>BT</i>	1	\$	546.00	\$	546.00
31	REAR LOWER ARM LH X	1	\$	689.00	\$	689.00
32	REAR KNUCKLE ARM LH ? - <i>BT</i>	1	\$	675.40	\$	675.40
33	REAR WHEEL BEARING LH ? - <i>APK jammed</i>	1	\$	321.00	\$	321.00
34	TAIL LAMP LH X	1	\$	756.70	\$	756.70
35	REAR BUMPER ✓ <i>BR</i>	1	\$	887.50	\$	887.50
36	REAR BUMPER SIDE RETAINER ✓ <i>BR</i>	12	\$	92.00	\$	184.00

Subtotal : \$ 16,189.50

Less 20% \$ 3,237.90

Parts Total : \$ 12,951.60

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE
1	REAR BUMPER CLIP SET ✓ <i>MC</i>	1	\$ 50.00	\$ <i>30</i> 50.00
2	REAR SPORT TYRE LH X	1	\$ 550.00	\$ 550.00
3	REAR DOOR INNER TRIM CLIP SET ✓ <i>MC</i>	1	\$ 50.00	\$ <i>20</i> 50.00
4	REAR WINDSCREEN SEALANT ✓ <i>MC</i>	1	\$ 80.00	\$ <i>40</i> 80.00
5	REAR WINDSCREEN INNER SEAL ✓ <i>MC</i>	1	\$ 50.00	\$ <i>20</i> 50.00
6	REAR FENDER INNER SHIELD CLIP SET ✓ <i>MC</i>	1	\$ 40.00	\$ <i>20</i> 40.00
7	REAR BUMPER CLIP SET ✓ <i>MC</i>	1	\$ 50.00	\$ <i>30</i> 50.00
8	ROCKER PANEL SEALANT X	1	\$ 120.00	\$ 120.00

\$ 990.00

LABOUR	PRICE
PANEL BEATING, REMOVAL AND REPLACING PARTS	<i>1200</i> \$ 1,800.00
TO SPRAY PAINT AFFECTED AREA	<i>1000</i> \$ 1,800.00
TO PERFORM LIGHTING & WIRING CHECK	<i>30</i> \$ 150.00
TO APPLY ANTI-RUST & TUFF KOTE	<i>30</i> \$ 250.00
REMOVE AND INSTALL FRONT DOOR PART	X \$ 180.00
REMOVE AND INSTALL REAR DOOR PART	<i>50</i> \$ 180.00
REMOVE AND INSTALL REAR WINDSCREEN	<i>120</i> \$ 250.00
REMOVE AND INSTALL CARPET, SEAT AND INTERIOR	<i>80</i> \$ 450.00
REMOVE AND INSTALL REAR UNDER CARRIAGE	<i>200</i> \$ 600.00
TO JACK AND REALIGNMENT CAR BODY BACK TO MANUFACTURING SPECIFICATION X	\$ 300.00
TO REPROGRAM, RESET AND CHECK ABS SYSTEM FUCTION	<i>60</i> \$ 600.00
TO CHECK FOUR WHEEL ALIGNMENT	<i>60</i> \$ 100.00

LABOUR TOTAL	\$ 6,660.00

Total Parts Cost	\$ 13,941.60
Total Labour Cost	\$ 6,660.00
Total Repair Cost	\$ 20,601.60

APPROVED DETAILS

NO. OF WORKING DAYS

PART BY PART OR LUMP SUM

DATE & TIME OF SURVEY

SURVEYED BY

CONTACT NUMBER

FAX NUMBER

Steve (LKK) WTL PL
27/4/21, 11.30am L/S

Ry AL sy
8 dys

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: