



Rico 60 Auto Services Pte Ltd
Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875
Email: claims@rico60.com
Tel: 6286 6060 Fax : 6286 7060

RICO Office Use Only

Parts -%	
SN	
Labour	
Total	
Lump Sum	
ERV	

TO: AXA

Vehicle No : SKZ 6900 X

Make & Model : MAZDA 3

DATE: 17/4/2021

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE
1	FRONT DOOR LH X NM	1	\$ 1,200.00	\$ 1,200.00
2	FRONT DOOR FRAME TOP RUBBER LH X NM	1	\$ 154.00	\$ 154.00
3	FRONT DOOR OUTER MOULDING LH X NM	1	\$ 199.60	\$ 199.60
4	FRONT DOOR INNER LOCK LH X NM	1	\$ 457.80	\$ 457.80
5	FRONT DOOR WEATHERSTRIP LH X NM	1	\$ 289.50	\$ 289.50
6	CENTER PILLER INNER TRIM LH X NM	1	\$ 541.00	\$ 541.00
7	ROCKER PANEL X R	1	\$ 1,245.00	\$ 1,245.00
8	REAR DOOR LH X R DD 1050	1	\$ 1,260.00	\$ 1,260.00
9	REAR DOOR FRAME TOP RUBBER LH ? X NM	1	\$ 89.00	\$ 89.00
10	REAR DOOR INNER STEP GARNISH LH X NM	1	\$ 124.00	\$ 124.00
11	REAR DOOR OUTER MOULDING LH ? X NM	1	\$ 198.00	\$ 198.00
12	REAR DOOR HINGE LH ? X NM	2	\$ 144.90	\$ 289.80
13	REAR DOOR CHECKER LH X NM	1	\$ 127.90	\$ 127.90
14	REAR DOOR OUTER HANDLE LH X NM	1	\$ 154.00	\$ 154.00
15	REAR DOOR OUTER HANDLE SIDE COVER LH X NM	1	\$ 67.60	\$ 67.60
16	REAR DOOR INNER LOCK LH Nec ? X NM	1	\$ 466.90	\$ 280 466.90
17	REAR DOOR LOCK CATCH LH X NM	1	\$ 56.00	\$ 56.00
18	REAR DOOR WEATHERSTRIP LH X NM	1	\$ 198.00	\$ 198.00
19	REAR DOOR CHANNEL LH X NM	1	\$ 96.00	\$ 96.00
20	REAR DOOR CHANNEL SEAL LH X NM	1	\$ 178.20	\$ 178.20
21	REAR DOOR REGULATOR MOTOR LH X NM	1	\$ 569.20	\$ 569.20
22	REAR DOOR REGULATOR GEAR LH ? X NM	1	\$ 316.00	\$ 316.00
23	REAR DOOR INNER TRIM LH ? X NM	1	\$ 758.10	\$ 758.10
24	REAR FENDER LH X R	1	\$ 1,241.00	\$ 1,241.00
25	REAR FENDER INNER SHIELD LH / TN	1	\$ 219.00	\$ 219.00
26	REAR FENDER QUARTER GLASS OUTER MLD X NM	1	\$ 158.00	\$ 158.00

27	REAR WINDSCREEN MOULDING	X	NN	1	\$	295.30	\$	295.30		
28	REAR WINDSCREEN INNER SEAL	X		1	NN	\$	60.00	\$	60.00	
29	REAR SPORT RIM LH	✓	CUT	1	\$	1,121.00	\$	1,121.00		
30	REAR ABSORBER LH		X	NN	1	\$	546.00	\$	546.00	
31	REAR LOWER ARM LH	X	NN	1	\$	689.00	\$	689.00		
32	REAR KNUCKLE ARM LH	James	X	NN	X	NN	\$	675.40	\$	675.40
33	REAR WHEEL BEARING LH		James	X	NN	\$	321.00	\$	321.00	
34	TAIL LAMP LH	X	NN	1	\$	756.70	\$	756.70		
35	REAR BUMPER		DR	1	\$	887.50	\$	887.50		
36	REAR BUMPER SIDE RETAINER		DR	1	2	\$	92.00	\$	184.00	
							Subtotal :	\$	16,189.50	
							Less 20%	\$	3,237.90	
							Parts Total :	\$	12,951.60	

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE
1	REAR BUMPER CLIP SET / MC	1	\$ 50.00	\$ 30 ✓ 50.00
2	REAR SPORT TYRE LH X NM	1	\$ 550.00	\$ 550.00
3	REAR DOOR INNER TRIM CLIP SET X NM	1	\$ 50.00	\$ 50.00
4	REAR WINDSCREEN SEALANT X NM	1	\$ 80.00	\$ 40 80.00
5	REAR WINDSCREEN INNER SEAL X NM	1	\$ 50.00	\$ 20 50.00
6	REAR FENDER INNER SHIELD CLIP SET / MC	1	\$ 40.00	\$ 20 ✓ 40.00
7	REAR BUMPER CLIP SET / MC	1	\$ 50.00	\$ 30 ✓ 50.00
8	ROCKER PANEL SEALANT X NM	1	\$ 120.00	\$ 120.00
			C.1 ✓	

		80	\$	990.00
LABOUR			PRICE	
PANEL BEATING, REMOVAL AND REPLACING PARTS	600 800		\$	1,800.00
TO SPRAY PAINT AFFECTED AREA	600 800		\$	1,800.00
TO PERFORM LIGHTING & WIRING CHECK	30		\$	150.00
TO APPLY ANTI-RUST & TUFF KOTE	30		\$	250.00
REMOVE AND INSTALL FRONT DOOR PART	X		\$	180.00
REMOVE AND INSTALL REAR DOOR PART	X		\$ 50	180.00
REMOVE AND INSTALL REAR WINDSCREEN	X		\$	250.00
REMOVE AND INSTALL CARPET, SEAT AND INTERIOR	X		\$	450.00
REMOVE AND INSTALL REAR UNDER CARRIAGE	X NN	100	\$	600.00
TO JACK AND REALIGNMENT CAR BODY BACK TO MANUFACTURING SPECIFICATION	X		\$	300.00
TO REPROGRAM, RESET AND CHECK ABS SYSTEM FUCTION	X NN	60	\$	600.00
TO CHECK FOUR WHEEL ALIGMENT	60		\$	100.00

1930 1480

LABOUR TOTAL		\$ 6,660.00
Total Parts Cost	\$	13,941.60
Total Labour Cost	\$	6,660.00
Total Repair Cost	\$	20,601.60

Steve (LKK) WHL PL
 27/4/21, 11. Nov L/S

APPROVED DETAILS
 NO. OF WORKING DAYS
 PART BY PART OR LUMP SUM
 DATE & TIME OF SURVEY
 SURVEYED BY
 CONTACT NUMBER
 FAX NUMBER

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Ry AL sy
 5 & dys

P- ~~2006.80~~ 3448.40
 NI- 80
 L - ~~1480~~ 1930
~~3566.80~~ 5458.40
 L/S- ~~2853.44~~ 4366.72
 = ~~2850~~ 4350