

HONDA

KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
 64 CECIL STREET
 #04-00 & #05-00 IOB BUILDING
 SINGAPORE 049711

Registration No : SCY3692R

Chassis No : JHMGK5850KS204458

Model : JAZZ 1.5VTIR CVT 19YM (EURO 6)

Owner's Name : CHOY WENG MENG

Ins Policy No. :

Date of Accident : 18/4/2021

Document No. : SQT21001346
Date : 19. Apr 2021
Customer No. : WZ1007
Svc Advisor : NG SIN HAI
Engine No : L15B34100250
Date | Time : 19. Apr 2021 4:54:15 PM
Surveyor Name :
Survey Date :
Authorisation Date :

| Item | Description | Qty | Unit Price | Disc % | Amount | 0% GST Amount | Amount incld GST |
|-----------------|-------------------------------|-----|------------|--------|---------|---------------|------------------|
| | TP DIRECT SETTLEMENT (J/NO:) | | | | | | |
| | OWNER: | | | | | | |
| | OWNER INSURER: | | | | | | |
| | ACC DATE: | | | | | | |
| | SURVEYED BY: | | | | | | |
| | DATE: | | | | | | |
| | REF NO: | | | | | | |
| | TP INSURER: | | | | | | |
| | TP VEH: | | | | | | |
| 04711-T5B-J50ZZ | FACE,FR.BUMPER X R | 1 | 497.20 | 25 | 372.90 | 26.10 | 399.00 |
| 71102-T5L-T80 | LOWER GRILLE ASSY,FR. X NM | 1 | 157.40 | 25 | 118.05 | 8.26 | 126.31 |
| 71103-T5B-J50 | GARNISH ASSY,R.FR.FOG X NM | 1 | 77.60 | 25 | 58.20 | 4.07 | 62.27 |
| 71104-T5B-J50 | COVER,FR.TOWING HOOK X NM | 1 | 7.70 | 25 | 5.77 | 0.40 | 6.17 |
| 71108-T5B-J50 | GARNISH ASSY,L.FR.FOG X NM | 1 | 77.60 | 25 | 58.20 | 4.07 | 62.27 |
| 71130-T5B-J50 | BEAM COMP,FR.BUMPER X NM | 1 | 319.70 | 25 | 239.77 | 16.78 | 256.55 |
| 71140-T5B-J60 | BEAM UPPER,R.FR.BUMPER X NM | 1 | 31.80 | 25 | 23.85 | 1.67 | 25.52 |
| 71193-T5A-000 | SPACERR.FR.BUMPER ? X NM | 1 | 10.40 | 25 | 7.80 | 0.55 | 8.35 |
| 71198-T5A-000 | SPACERL.FR.BUMPER X NM | 1 | 10.40 | 25 | 7.80 | 0.55 | 8.35 |
| 91505-TM8-003 | CLIP,BUMPER / N/C | 15 | 2.30 | 25 | 25.87 | 1.81 | 27.68 ✓ |
| 71121-T5B-J50 | BASE,FR.GRILLE HOOK X NM | 1 | 264.60 | 25 | 198.45 | 13.89 | 212.34 |
| 71123-T5B-J60 | MOLDING UPPER,FR.GRILLE X NM | 1 | 145.50 | 25 | 109.12 | 7.64 | 116.76 |
| 75700-T5A-000 | EMBLEM H X NM | 1 | 17.20 | 25 | 12.90 | 0.90 | 13.80 |
| 90301-ST0-003 | NUTPUSH 3MM X NM | 2 | 2.10 | 25 | 3.15 | 0.22 | 3.37 |
| 60211-T5R-A00ZZ | PANEL ,R.FR.FENDER / DO | 1 | 425.10 | 25 | 318.82 | 22.32 | 341.14 ✓ |
| 74100-TAS-000 | FENDER ASSY,R.FR. ? / CRU | 1 | 84.60 | 25 | 63.45 | 4.44 | 67.89 ✓ |
| 91501-TR0-003 | CLIP,INNER FENDER X NM | 11 | 2.80 | 25 | 23.10 | 1.62 | 24.72 |
| 33100-T5A-T21 | LIGHT ASSY,R.HEAD ? X NM | 1 | 1664.80 | 25 | 1248.60 | 87.40 | 1336.00 |
| 44600-T5B-J00 | HUB ASSYFR. X NM | 1 | 138.30 | 25 | 103.72 | 7.26 | 110.98 |

Printed on 19/4/2021 5:45:52 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

HONDA

KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair

QUOTATION

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Tel: +65 6841 3838
 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

| | | | | | |
|-------------------------|--|---------------------|---------------------------|---------------------------|----------------|
| Customer | : INDIA INTERNATIONAL INSURANCE PTE 64 CECIL STREET #04-00 & #05-00 IOB BUILDING SINGAPORE 049711 | Document No. | : SQT21001346 | Page | 2 |
| Registration No | : SCY3692R | Date | : 19. Apr 2021 | Customer No. | : WZ1007 |
| Chassis No | : JHMGK5850KS204458 | Svc Advisor | : NG SIN HAI | Engine No | : L15B34100250 |
| Model | : JAZZ 1.5VTIR CVT 19YM (EURO 6) | Date Time | : 19. Apr 2021 4:54:15 PM | Surveyor Name | : |
| Owner's Name | : CHOY WENG MENG | Survey Date | : | Authorisation Date | : |
| Ins Policy No. | : | | | | |
| Date of Accident | : 18/4/2021 | | | | |

| Item | Description | Qty | Unit Price | Disc % | Amount | 0% GST Amount | Amount incld GST |
|-------------------------|---|-----|---------------------------|---------------|----------------|---------------|------------------|
| 44300-TD4-J51 | BEARING ASSY,FR.HUB X <i>R/N</i> | 1 | 141.60 | 25 | 106.20 | 7.43 | 113.63 |
| 42700-TAR-E91 | DISK ALUMINIUM WHEEL,16X6 <i>? (Try Polih) X 1R</i> | 1 | 262.70 | 25 | 197.02 | 13.79 | 210.81 |
| Sum Item | | | | | 3302.74 | 231.17 | 3,533.91 |
| BOSUN | SUNDRIES | 1 | 100.00 | <i>30 /</i> | 100.00 | 7.00 | 107.00 |
| BML011 | INSPECT FR LIGHTING MECHANISMS & FOCUS | 1 | 180.00 | <i>150 /</i> | 180.00 | 12.60 | 192.60 |
| BC012R | RESET VEHICLE SMART ENTRY SYSTEM | 1 | 650.00 | <i>580 /</i> | 650.00 | 45.50 | 695.50 |
| BKBU01R | REMOVE & RENEW FR BUMPER INCLUDING FITTINGS ON | 1 | <i>2 dy - 650</i> 2000.00 | <i>1300 /</i> | 2000.00 | 140.00 | 2140.00 |
| BP03R | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P) | 1 | <i>2M - 520</i> 2000.00 | <i>1040 /</i> | 2000.00 | 140.00 | 2140.00 |
| BMU12R | REMOVE & REPLACE FR R UNDERCARRIAGE PARTS. (N) | 1 | 1200.00 | <i>X 2</i> | 1200.00 | 84.00 | 1284.00 |
| BOSUN | REMOVE AND RENEW RHF WHEEL/RIM/TYRE <i>650</i> | 1 | 50.00 | <i>X 2</i> | 50.00 | 3.50 | 53.50 |
| Sum Labor | | | | | 6180.00 | 432.60 | 6,612.60 |
| BO-WHEEL ALIGN X4 | WHEEL ALIGNMENT X4 | 1 | 180.00 | <i>X</i> | 180.00 | 12.60 | 192.60 |
| Sum Ext. Service | | | | | 180.00 | 12.60 | 192.60 |

Survey By: Steve (LKK) *Steve*
 Date & Time: 28/4/21, 19.30a
 Excess: PP
 Status: By Del ay
 Signature: 4 dys

Total Amount 9,662.74 676.37 10,339.11
Total (Inclusive of GST) 10,339.11

Printed on 19/4/2021 5:45:52 PM
 This is a computer generated invoice. No signature is required.
 Part prices are subjected to change without notice.
 The above estimated cost of repair do not include any unforeseen damages.
 GST Amount is calculated from individual line(s).
 An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00, lodged by Repairer.
 However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices may be subject to change
- Third party survey is on a "Without prejudice" basis
- No illegal modification shall be allowed
- Supplementary items shall be surveyed and is subject to final approval from insurance Company

Signature: _____
 Date: _____



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

| | | | |
|--------------------|-----------------------|-------------------------|----------------|
| Customer: | CU0118291 / CHOY WENG | Document No: | SVO21023512 |
| Chassis No: | JHMGK5850KS204458 | Printed By: | SHNG |
| License No: | SCY3692R | Order Date: | 28. April 2021 |
| Mileage: | 7759 | Order Time: | 11:05:00 AM |
| Engine No: | L15B34100250 | Service Advisor: | NG SIN HAI |

| ITEM | DESCRIPTION | QTY | UNIT PRICE | DISC % | AMOUNT | 7% GST Amount | Amount incld GST |
|---------------|---|-----|------------|--------|----------------------------|---------------|------------------|
| 74100-TAS-000 | SUPPLEMENTARY ITEM FENDER ASSY,R.FR. | 1 | 84.60 | 25 | 63.45 | 4.44 | 67.89 |
| | | | | | SUM PARTS: | 63.45 | 4.44 |
| | | | | | TOTAL SGD | 63.45 | 4.44 |
| | | | | | Total Payable (SGD) | | 67.89 |

GST Amount is calculated from individual line(s)