

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBD6996S210412

Estimate**Customer**

Name: AIG Asia Pacific Insurance Pte Ltd

Address Motor Claims Department

78 Shenton Way #07-16

AIG Building Singapore 079120

Date: 19-04-21

Vehicle No: GBD6996S

Model/Make: Toyota Hiace

Van Turbo 5 DR Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 300.00	200
2	To putty & spray painting & including touch up paint on accident affected areas	\$ 300.00	300
3	To apply Rust Proofing , reseal tuff-coating treatment on accident area	\$ 60.00	X

Total Parts & Labour of estimate for damaged vehicle

\$ 660.00

Total amount in Lump Sum Basis for repaired vehicle

SDLS: _____



M/s Liu's Bro Auto Engrg Wks

Not Referral
 20/4/21
 P/P \$ 500 /
 2 days.
 Hkh - HS1A0 70N6

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: