

Indeco

No. 39 DEFU LANE 12, SINGAPORE 539139

VEHICLES & EQUIPMENT DIVISION Tel: (65) 382 2736 FAX: (65) 6382 2817

ACCIDENT REPAIR ESTIMATES

Our Ref: OD / SLT7649K

Type of Claim : TPVehicle No. : SLT7649KMake & Model : BLUECARYear of Manufacture : 2017Chassis No. : VL4BCEB4RHT002949Ins Company : INDIA INTERNATIONALExcess : INSURANCEDate of Accident : 09/04/2021Engine No. : Policy No. : SD21V00611/VPZ/R01Time of Accident : Suggested Days of Repair : 8Case Owner : BLUECAR EAST ASIA PTE LTDTP Vehicle No. : SLM1606K**Repair Estimates**

Parts (a) Cost / List Price Items	\$ 4,313.00
Plus/Less— 20.0%	\$ 862.60
Total of Cost / List	\$ 5,175.60
(b) Nett Price Items	\$ -
Less	\$ -
Total of Nett Item	\$ -
(c) Special Nett Items	\$ 305.00
Total Parts Cost (Appendix A)	\$ 5,480.60
Labour (Appendix B)	\$ 1,750.00
Total Repair Cost	\$ 7,230.60

Steve (LKK)
20/4/21, 11.00am

we AL
4 dys
P/P
My Bel spg

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Company : Survey conducted on : at **Remarks By Surveyor**

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ (e) Signature of surveyor : Date:

Indeco

VEHICLES & EQUIPMENT DIVISION

No. 39 DEFU LANE 12, SINGAPORE 539139

Tel: (65) 382 2736 FAX: (65) 6382 2817

FINALIZATION REPAIR COST DETAILS

Vehicle No : SLT7649K Case Owner : BLUECAR EAST
Make & Model : BLUECAR Year Manufacture : ASIA PTE LTD
Chassis No : VL4BCEB4RHT002949 Engine No : 0
Date & Time : Supplier :
Order By : Type of Claim : TP

S/No	Part Description	QTY	Cost Price		List Price	Nett Price	S/N
			Unit	Sub-Total			
1	BOOT LID GLASS / OR	1	\$ 966.00	\$ 966.00			
2	HATCH PININFARINA LOGO / nec	1	\$ 32.00	\$ 32.00			
3	HATCH PININFARINA EMBLEM / nec	1	\$ 62.00	\$ 62.00			
4	BOOT LID GLASS SCREW COVER / CUT	12	\$ 18.00	\$ 72.00			
5	BOOT LID GLASS SCREW COVER / nec	4	\$ 2.00	\$ 8.00			
6	BOOT LID GLASS HINGE ASSY X	1	\$ 154.00	\$ 154.00			
7	BOOT LID GLASS DAMPER RH X	1	\$ 36.00	\$ 36.00			
8	BOOT LID GLASS DAMPER LH X	1	\$ 36.00	\$ 36.00			
9	BOOT LID GLASS LOCK X	1	\$ 132.00	\$ 132.00			
10	BOOT LID GLASS LOCK CATCH X	1	\$ 55.00	\$ 55.00			
11	BOOT LID GLASS CATCH COVER X	1	\$ 35.00	\$ 35.00			
12	REAR BOOT LID STICKER X	1		\$ -			\$ 40.00
13	REAR WEATHER STRIP / TN	1	\$ 84.00	\$ 84.00			
14	REAR TRIM ?	1	\$ 128.00	\$ 128.00			
15	REAR LH TAILAMP ASSY / CUT	1	\$ 151.00	\$ 151.00			
16	REAR LH TAILAMP FRAME / CUT	1	\$ 106.00	\$ 106.00			
17	REAR BUMPER / OR ?	1	\$ 1,405.00	\$ 1,405.00			
18	REAR BUMPER REINFORCEMENT ?	1	\$ 82.00	\$ 82.00			
19	REAR BUMPER REINFORCEMENT BRACKET ?	2	\$ 43.00	\$ 86.00			
20	REAR BUMPER NUMBER PLATE LIGHT X	2	\$ 105.00	\$ 210.00			
21	REAR LH FENDER COVER X	1	\$ 194.00	\$ 194.00			
22	REAR BUMPER REFLECTOR LH ?	1	\$ 125.00	\$ 125.00			
23	REAR LH FENDER INNER SHIELD ?	1	\$ 154.00	\$ 154.00			
24	REAR FENDER STICKER LH / nec	1					\$ 40.00
25	REAR BUMPER MARKETING DECAL / nec	1					\$ 180.00
26	REAR NUMBER PLATE / OR	1					\$ 45.00
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

TOTAL

\$ 4,105.00 \$ 4,313.00 \$ - \$ - \$305.00



VEHICLES & EQUIPMENT DIVISION

No. 39 DEFU LANE 12, SINGAPORE 539139

Tel: (65) 382 2736 FAX: (65) 6382 2817

Labour

Vehicle No. : SLT7649K
Make & Model : BLUECAR

Case Owner
Year of Manufacture

BLUECAR
EAST ASIA
PTE LTD
2017

S/No	Labour Description	Estimated Price	Adjusted Price
1	LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.	\$1,000.00	250 375
2	TO PUTTY, RESPRAY REAR FENDER AND REAR BUMPER	\$600.00	400
3	TO REPLACE REAR WINDSCREEN GLASS & CLEAN UP SHATTERED GLASS	\$150.00	120
Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal work to be carried out • Supplementary work to be carried out and is subject to final approval from insurance Company Acknowledged by Repairer Signature: Date:			
TOTAL		\$ 1,750.00	

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.