



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21004918/Euf3e2	
			Date: 29/04/2021	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMB 339J	Veh. Inspected	SJE 6869B
	Policy No.		Coverage (\$)	0.00
	Claim No.	BUS/04/21/5013/JF	Excess (\$)	0.00
	Assign From	ASHLENE LEE	Assign Date	20/04/2021
2. Vehicle Particulars & Condition				
	Make & Model	HONDA AIRWAVE	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	GJ11207754	Colour	SILVER
	Odometer	191665 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	MICHELIN	4 mm
	L/H Front Tyre	185/60 R15	MICHELIN	4 mm
	R/H Rear Tyre	185/60 R15	MICHELIN	4 mm
	L/H Rear Tyre	185/60 R15	MICHELIN	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	07/04/2021	Inspection Date	21/04/2021
	Survey held at	Block 7, Woodlands Road 01-397D, Yew Tee		
	Repairer	JOHN AUTO SERVICES		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	