

JOHN AUTO SERVICES

(53315321B)

BLK, E5, 395A WOODLANDS ROAD,
YEW TEE INDUSTRIAL ESTATE,
SINGAPORE 677984

JOHN AUTO SERVICES

(53315321B)

Blk 7, 397-D Woodlands Road
Yew Tee Industrial Estate
Singapore 677996 HP: 85081258

hingle motu @ yata.com.sg

SJE 6869B

Date

20/4/21

NO

1.	Rear bumper / CRU	\$ 1189.20	1078.50 /
2	Rear RH bumper side holder - OR	\$ 48.40	/
3.	Rear tail lamp bezel RH - OR	\$ 258.40	/
4.	Rear RH fender - DO	\$ 1105.80	991.20 /
5	Rear Knuckle axle ? / RT	\$ 1458.30	/
6	Rear Knuckle Bearing ? / Jammed	\$ 288.10	/
7	Rear RH fender gloss moulding 1 set / MC	\$ 65.00	/
8	Rear Shock Absorber RH ? X NM	\$ 330.10	
9	1 Set Interior Trim Board Clip X / MC	\$ 45.00	SN .20 /
10	1 Set Rear bumper Clip - MC	\$ 45.00	SN .30 /
11	1 Rear RH wheel Rim - OR	\$ 580.00	SN 420 /
12.	1 Rear RH Tyre - TN	\$ 100.00	SN /
13	1 Set Rear bumper Sensor X NM	\$ 220.00	SN
14	Rear tail gate X NM	\$ 1787.00	
15	Rear glass Moulding X NM	\$ 120.00	
16	Rear glass Sealant X / (Rear RH) / MC	\$ 50.00	SN 40 /

Steve

22/4/21

JOHN AUTO SERVICES

(53315321B)

Blk 7, 397-D Woodlands Road
Yew Tee Industrial Estate
Singapore 677984 HP: 85081258

JOHN AUTO SERVICES

(53315321B)

BLK, E5, 395A WOODLANDS ROAD,
YEW TEE INDUSTRIAL ESTATE,
SINGAPORE 677984

JOHN AUTO SERVICES
(53315321B)

Blk 7, 397-D Woodlands Road
Yew Tee Industrial Estate
Singapore 677996 HP: 85081258

SSE 6869 B

Date 20/4/21 NO.

Labour Charge.

1.	Rear bumper Sensor Refit	\$ 60.00.	30 /
2.	Wiring fee	\$ 40.00.	30 /
3.	Anti Rust ^{glass}	\$ 60.00.	30 /
4.	Rear RH fender TOP Refit	\$ 80.00.	50 /
5.	Rear Under Carriage Remove & Replace	\$ 300.00.	200 /
6.	Rear Boot interior Remove & Refit	\$ 100.00.	50 /
7.	2 time wheel alignment	\$ 100.00.	60 /
8.	Roof lining Remove & Refit	\$ 100.00.	30 /
9.	To Respray Painting Damage area	\$ 800.00.	450 450 /
10.	To Remove & Replace Cut & Weld	\$ 800.00.	700 /
11.	To Remove & Refit Rear glass	\$ 120.00.	X

STER CLKK) 83228813

21/4/21, 12.00pm

Wt AL

5 days

My AL sy

JOHN AUTO SERVICES

(53315321B)

Blk 7, 397-D Woodlands Road
Yew Tee Industrial Estate
Singapore 677996 HP: 85081258

S/S

22/4/21

Parts - 4197.30

Nett - 610

Labour - 1630

- 20%

= 5597.84

3357.84

L/S - 4478.27

= 4500