

SERVICE ESTIMATE

98822 - C00001
Mr Lau Tze Siang
BLK 635B Senja Road
#21-261
Singapore
Singapore 672635

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 1
Inv.date. : 07/04/2021
WIP No. . : 18905
Veh.In/Out:
*Tel.No. . : Mobile: 98896585
Reg.No. . : SMF6585D
Reg.date . : 20/11/2018
Mileage . : 0
Chassis No: VF1RFA00861136826

Closed by : Michelle Ong Siew Be
Svc Consultant :
Remarks : Mr Lau Tze Siang

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE BONNET, FRONT BUMPER, GRILLE TOP PANEL, FRONT GRILLE, GRILLE CHROME MOULDING, LOGO, BRACKETS, ETC. @SSV	0	1650.00	0		1,650.00 S 1100/-	
800	TO PUTTY AND SPRAY PAINT ON BONNET, FRONT BUMPER, ETC. @SSV	0	1500.00	0		1,500.00 S 1000/-	
802	TO REPLACE REAR BUMPER, REAR BLACK BUMPER SPOILER, BOOT SILL, ETC. @SSV	0	1100.00	0		1,100.00 S 550/-	
800	TO PUTTY AND SPRAY PAINT ON REAR BUMPER, ETC. @SSV	0	1000.00	0		1,000.00 S 500/-	
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	588.00	0		588.00 S /	
R06	TO REPLACE FRONT NUMBER PLATE W HOLDER. @SSV	0	60.00	0		60.00 S /	
	BONNET FRT GS4	1.0 EA	1225.10			1,225.10 S 1102.59	

Rasul

HP 90010068

7 days

18/05/21 @ 1050

Resin before paint

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Wearnes Automotive Pte. Ltd.

Leng Kee Road, Singapore 159103 T +65 6430 4700 www.wearnesauto.com

reg no. 199501400R / GST reg no. M28920628X

Accident report 0200210001

SERVICE ESTIMATE

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

*Tel.No. . : Mobile: 98896585

Reg.date. : 20/11/2018

Chassis No: VF1RFA00861136826

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

BUMPER FRT TOP GRILL	cm	1.0 EA	431.10	431.10 S	387.99
GRILLA LINING PANEL	? scu	1.0 EA	314.00	314.00 S	282.60
GRILLA TOP CHROMA ST	cm	1.0 EA	208.80	208.80 S	187.92
BUMPER TOP GRILLA OU	? cm	1.0 EA	252.30	252.30 S	221.07
LOGO FRT GRILLE GS4	mis	1.0 EA	148.40	148.40 S	133.56
STICKER M4S	new	1.0 EA	15.50	15.50 S	13.95
BUMPER FRT GS4	cm	1.0 EA	1295.50	1,295.50 S	1165.95
TOW COVER FRT GS4	X scu	1.0 EA	108.60	108.60 S	
BUMPER FRT SUPPORT B	? cm	1.0 EA	115.10	115.10 S	103.59
BUMPER UNDER COVER F	? scu	1.0 EA	566.80	566.80 S	
CONVERGENT AIR GUIGE	? scu	1.0 EA	137.80	137.80 S	
FOG LAMP FRT INNER B	? scu	1.0 EA	180.70	180.70 S	
BUMPER LOWER FRT GS4	? scu	1.0 EA	431.10	431.10 S	
BUMPER FRT CENTER IN	? cm	1.0 EA	226.50	226.50 S	203.85
BUMPER FRT TOP INNER	? scu	1.0 EA	398.40	398.40 S	
FOG LAMP MOULDING OU	? scu	1.0 EA	221.80	221.80 S	
FOG LAMP COVER CHORM	? scu	1.0 EA	221.80	221.80 S	

SERVICE ESTIMATE

98822 - C00001
Mr Lau Tze Siang
BLK 635B Senja Road
#21-261
Singapore
Singapore 672635

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 3

Inv.date. : 07/04/2021

WIP No. . : 18905

Veh.In/Out:

*Tel.No. . : Mobile: 98896585

Reg.No. . : SMF6585D

Reg.date. : 20/11/2018

Mileage . : 0

Chassis No: VF1RFA00861136826

Closed by : Michelle Ong Siew Be
Svc Consultant :
Remarks : Mr Lau Tze Siang

Op.No	Description	Mech Qty	Price Disc% Pkg	Amount G
	SUPPORT BRACKET, HEA <i>? x su</i>	2.0 EA	153.00	306.00 S
	BUMPER BRACKET FRT R <i>? x su</i>	1.0 EA	131.00	131.00 S
	BUMPER BRACKET FRT L <i>? x su</i>	1.0 EA	131.00	131.00 S
	BUMPER FRT REINFORCE <i>? x su</i>	1.0 EA	662.70	662.70 S
	HEADLAMP RH R9A3 GS4 <i>cm</i>	1.0 EA	820.70	820.70 S <i>738.63</i>
	HEADLAMP LH R9A3 GS4 <i>x su</i>	1.0 EA	820.70	820.70 S
	BUMPER REAR GS4 BOSS <i>cm</i>	1.0 EA	928.50	928.50 S <i>835.65</i>
	TOWING COVER REAR BU <i>3 su</i>	1.0 EA	83.00	83.00 S <i>74.70</i>
	BUMPER REAR PAD GS4 <i>? x su</i>	1.0 EA	483.20	483.20 S
	BUMPER REAR LOWER MO <i>? x su</i>	1.0 EA	555.30	555.30 S
	BUMPER REAR BRACKET <i>? x su</i>	1.0 EA	268.70	268.70 S
	BUMPER REAR BRACKET <i>? x su</i>	1.0 EA	267.10	267.10 S
	BUMPER REAR CENTER B <i>? x su</i>	1.0 EA	333.00	333.00 S
	BUMPER REAR LH SUPPO <i>? x su</i>	1.0 EA	106.00	106.00 S
	BUMPER REAR RH SUPPO <i>x su</i>	1.0 EA	106.00	106.00 S
	BUMPER REAR BRACKET <i>x su</i>	1.0 EA	157.30	157.30 S
	BUMPER REAR BRACKET <i>x su</i>	1.0 EA	136.70	136.70 S

SERVICE ESTIMATE

98822 - C00001
Mr Lau Tze Siang
BLK 635B Senja Road
#21-261
Singapore
Singapore 672635

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 4

Inv.date. : 07/04/2021

WIP No. : 18905

Veh.In/Out:

*Tel.No. : Mobile: 98896585

Reg.No. : SMF6585D

Reg.date. : 20/11/2018

Mileage : 0

Chassis No: VF1RFA00861136826

Closed by : Michelle Ong Siew Be
Svc Consultant :
Remarks : Mr Lau Tze Siang

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

	BUMPER PAD SUPPORT B <i>? x su</i>	1.0 EA	81.20			81.20	S
	BUMPER RR CENTER UND <i>X su</i>	1.0 EA	411.50			411.50	S
	BUMPER RR RH UNDER C <i>X su</i>	1.0 EA	279.10			279.10	S
	BUMPER RR LH UNDER C <i>X su</i>	1.0 EA	218.80			218.80	S
	LAMP FOG, REAR LH S4 <i>? x su</i>	1.0 EA	346.00			346.00	S
	LAMP-FOG, REAR RH GS <i>X su</i>	1.0 EA	238.50			238.50	S
	BUMPER REAR REINFORC <i>? x su</i>	1.0 EA	639.20			639.20	S
	ADHESIVE SEALER FL2 <i>? x su</i>	1.0 EA	709.60			709.60	S
	BODY PANEL SEALANT X <i>? x su</i>	1.0 EA	1019.00			1,019.00	S
	PRIMER <i>? x su</i>	1.0 EA	185.60			185.60	S
	BOOT SILL PLATE "G/S" <i>? su</i>	1.0 EA	318.90			318.90	S

Gross Total. 23,141.60

Net..... 23,141.60

GST @ 7.0% 1,619.91

Total..... 24,761.50

Paid..... 0.00

Please Pay.. 24,761.50

Labour Total 5,898.00
Parts Total 17,243.60
Package Total 0.00

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

Wearnes Automotive Pte. Ltd.

Eng Kee Road, Singapore 159103 T +65 6430 4700 www.wearnesauto.com

Reg no. 199501400R / GST reg no. M28920628X