

SERVE YOU MOTOR PTE LTD

Blk 5033 Ang Mo Kio Ind. Pk 2
#01-265 (S) 569536

Tel: 6481 0555 Fax: 6483 1654
E-mail: elainesyms@gmail.com

Not Authorized
6/1/2021 4:00pm
Resman Alen Paim
6 days

INS: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
Owner: TEO THIARC-HNG, BASIL

Registration no. SLJ6970R Mitsubishi Outlander 2.4 CVT AWD S/R
Accident Date: 17/04/2021

Date 22/4/2021

Quotation No: 2021-04-0017

S/N	Qty	Particulars	Units Price	Amount
-----	-----	-------------	-------------	--------

LIST ITEMS

1	1	Tailgate 984		R 1,180.00 ✓
2	1 set	Tailgate Centre Emblem		na 48.00 ✓
3	1	Tailgate Outlander Emblem		na 74.00 ✓
4	2	Tailgate MIVEC Emblem		na 55.00 ✓
5	1	Tailgate Garnish with Chrome Moulding 416	Ref	6 486.00 X
6	2	Tailgate Reflectors	\$389.00	sm 778.00 X
7	1	Tailgate Inner Lock		Tr 428.00 ✓
8	1	Tailgate Lock Button		sm 28.00 X
9	1	Tailgate Lock Striker		R 25.00 X
10	1	Tailgate Innes Trimboard		sm 320.00 X
11	1	Tailgate Inner Trimboard Clip (Set)		na 40.00 X
12	1	Tailgate Weatherstrip		na 188.00 50lin
13	1	Rear Bumper 873		Ref/CM 881.00 ✓
14	2	Rear Bumper side retainer	cls n/v \$34.00	68.00 ✓
15	2	Rear Bumper Lower Reflector	ols cm \$114.00	228.00 ✓
16	1	Rear Bumper Lower Lip		CM 340.00 ✓
17	2	Licence Plate Lamp	\$30.00	sm 60.00 X
18	2	Rear Tail Lamp	\$595.00	sm 1,190.00 X
19	2	Rear Bumper Bracket	\$80.00	R 160.00 X
20	1	Rear Bumper Buzzer		cm 85.00 ✓
21	1	Rear End Panel 496		R 850.00 ✓
22	1	Rear Ebd Panel Top Trim 146		Ref 185.00 ✓
23	1	Rear Bumper Keyless Antenna		sm 132.00 X
24	1	Spare Tyre Carrier		na 355.00 ✓
25	1	Spare Tyre Carrier Bracket		R 45.00 X
26	1	Spare Tyre Carrier Bolt		sm 35.00 X
27	1	Spare Tyre Carrier Holder		sm 18.00 X
28	1	Spare Tyre Carrier Spacer		sm 25.00 X
29	2	Cylinder Head Washer	\$12.00	NIP 24.00 X
30	1	Rear Windscreen Moulding 120		na 260.00 ✓

sub-total: 7,411.00
Less 10% -690.70
6,720.30

SERVE YOU MOTOR PTE LTD

Blk 5033 Ang Mo Kio Ind. Pk 2

#01-265 (S) 569536

Tel: 6481 0555 Fax: 6483 1654

E-mail: elainesyms@gmail.com

INS: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Owner: TEO THIARC-HNG, BASIL

Registration no. SLJ6970R Mitsubishi Outlander 2.4 CVT AWD S/R

Accident Date: 17/04/2021

Date 22/4/2021

Quotation No: 2021-04-0017

LABOUR & MISC CHARGES

1	Check Wiring and Lighting	60.00	201
2	Remove abd Replace Reverse Sensor Assy	80.00	501
3	Remove and Replace Reverse Camera Assy	80.00	401
4	Apply Anti-Rust Prounting on Effected Areas	100.00	601
5	Remove and Refix Rear Windscreen Glass	150.00	1201
6	Transfer Tailgate Part	100.00	601
7	Remove and Refix Rear upholstery ,Trimming	150.00	601
8	Conduct Water Seepage Test	80.00	201
9	Perform Diagnostic check for Fault and Reset to Factory Setting	200.00	X
10	Panel Beat and Replace Damage Parts on Affected Area	1,600.00	8001 7501
11	Putty and Spray Painting on Affected Area	1,800.00	8001
TOTAL		5,000.00	
Total Parts and Labour Cost of Repair		\$12,176.30	