

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/III21004930/EGS3Q2

Date:

05/07/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

D19MFL0005549_01

Claimant Vehicle No : SMV5533B**Insured Vehicle No :**

GBH7365K

Date of Loss: 16/04/2021

Nature of Claim:

TP

Claim No:

MFL2021D0001666

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMV5533B**

Make & Model: MITSUBISHI ATTRAGE, 1.2 CVT (A)

Engine No: 3A92UJS5665

Reg. Date: 07/10/2020 (Man. Year: 2020)

Chassis No: MMBSTA13AMH001323

Colour: Grey

Odometer: 32553 km

Engine Capacity: 1193 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R15

Rear Tyre Size:

185/55 R15

Front Left Side: Bridgestone 5 mm

Rear Left Side:

Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm

Rear Right Side:

Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	674.00	674.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,630.00	1,550.00	80.00	4.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,304.00	2,224.00	80.00	3.47
+ GST 7.00/7.00% (S\$)	161.28	155.68	5.60	3.47

Nett Amount (S\$)	2,465.28	2,379.68	85.60	3.47
+ Car Rental (5.0 x S\$100.00/day + 7.00% GST) (S\$)		535.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,922.13		

INSPECTION

Date of Assignment: 20/04/2021

Date Inspected: 12/05/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
 209 Pandan Gardens
 Singapore 609339

Adjuster: CHEN TSUE YEE**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 May 2021)	
Parts:	N/A	MITSUBISHI ATTRAGE 1.2 CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMV5533B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACE ,RR BUMPER	Dented	654.00 FS	*654.00 FS
2	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
					Total Parts (S\$)	674.00
						674.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RENEW REAR BUMPER	New	700.00	640.00
2	SPRAY PAINT FOR REAR BUMPER	New	550.00	550.00
3	REMOVE & INSTALL PARKING SENSOR	New	100.00	80.00
4	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	280.00	280.00
Gross Labour Cost (\$\$)			1,630.00	1,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >