

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
PHAY KOK BENG 576 WOODLANDS DRIVE 16 #10-506 SINGAPORE 730576 Contact No	Cust No/Name	KCV16118/PHAY KOK BENG
	Reg No/Reg Date	SMV5533B / 07/10/202
	Date In/Mileage	/ 0
	Chassis No	MMBSTA13AMH001323
	Engine No	3A92UJS5665
	Make/Model	MIT/21MY ATTRAGE 1.2 CVT (E31)
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KCV16118	CRDVCH	19/04/2021/ 18:02	Bod	442 / CocoLu	10246			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW REAR BUMPER								700.00
E PNT98000 SPRAY PAINT FOR REAR BUMPER								550.00
E PNT88000 REMOVE & INSTALL PARKING SENSOR								100.00
M SUNDRY Sundry								20.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								280.00
M FACE,RR BUMPER					1.00	654.00	00.00	654.00

Confirm & accepted by

Nett	2,304.00
7% GST on	161.28
Total Payable	2,465.28

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.